
John Brown's Fort Building 63

HFR. 201

Harpers Ferry National Historical Park Flood / Storm Recovery Project

Condition Assessment Report and Preservation Repairs

February 1998



Prepared by: National Park Service Historic Preservation Training Center 4801 A Urbana Pike / Gambrill House Frederick, Maryland 21704

TABLE OF CONTENTS

I.	INTRODUCTION	2
II.	EXECUTIVE SUMMARY	5
III.	BRIEF CHRONOLOGY	8
IV.	EXISTING CONDITIONS	11
	General Site North Elevation South Elevation East Elevation West Elevation Roof and Cupola Interior	11 11 12 13 14 15 15 16
V.	PRESERVATION TREATMENT RECOMMENDATIONS	19
	Site Masonry Windows Doors Roof Cupola	19 19 20 21 21 22
VI.	PRIORITIZED TREATMENT RECOMMENDATIONS	24
VII.	BUDGET ESTIMATES	. 27
	Summary of Costs Class "B" Cost Estimates	27 28

VIII.	PHOTOGRA	PHS	31
IX.	APPENDIX	Α	45
	Field	Notes	45
X.	APPENDIX	В	63
	1976 (Construction Drawings Partial Restoration of John Browns Fort Drawing No. 385 / 25003 (DSC) 13 sheets, dated November 1978 Denver Service Center	63
	1998 1	Preservation Treatment Drawings Condition Assessment Report and Preservation Repairs Drawing No. 385 / 80103 (NCR) 10 sheets, dated January 1998 Historic Preservation Training Center	76
XI.	APPENDIX	С	88
	Projec	et Agreement	88

I. INTRODUCTION

D. Project Responsibilities

Donald Campbell ,Superintendent,Harpers Ferry National Historical Park Bruce Noble, Chif of Cultural Resources, Harpers Ferry National Historical Park Tim Fox, Chief of Maintenance, Harpers Ferry National Historical Park Bob Wilhide, Maintenance Supervisor, Harper Ferry National Historical Park Peter Dessauer, Park Architect, Harpers Ferry National Historical Park Tom McGrath, Superintendent, Historic Preservation Training Center Doug Hicks, Assistant Superintendent, Historic Preservation Traing Center Tom Vitanza, Historical Architect/Project Supervisor, Historic Preservation Training Center

Chris McGuigan, Team Leader/Exhibit Specialist, Historic Preservation Training Center Anthony S. Donald, Project Architect, Denver Service Center, Architecture

E. Compliance

The 106 compliance for flood/storm repairs to John Brown's Fort, Harpers Ferry National Historical Park, Historic Structure # 63, are covered in a 1997 programmatic agreement between the park and the State Historic Preservation Officer in West Virginia.

II. EXECUTIVE SUMMARY

II. EXECUTIVE SUMMARY

The John Brown Fort has a number of problems which fall primarily into the categories of masonry, carpentry and millwork, all of which all can be addressed and corrected through the use of in-house preservation and maintenance staff. While there are no critical fabric or structural issues that fall into a life safety concern, the current conditions will accelerate if left untreated, and may become a hazard if not corrected.

The major areas of masonry deterioration fall into two zones. The first zone is at the base of the structure. The stone water table and the fifteen courses (plus or minus) of brick above the water table have been subject to numerous submersions by the rising rivers of the Shenadoah and the Potomac. The mortar joints in the stone water table are for the most part non existant and need replacement, while the mortar joints for the brick are extremely soft and can be raked out without much effort. The mortar joints for the entire lower portion of the building should be raked out and repointed. It is recommended that a more moisture resistant mortar be used at the lower courses to help prevent deterioration when future flooding does occur. The other masonry repair zone is at the top of the end walls of the structure. The two gable end walls form a parapet wall, above the roof line, that is exposed to the elements on both sides . The soft brick combined with freeze/ thaw cycles has caused these areas to deteriorate at a faster rate. It is recommended that these gable end parapet walls be raked out and repointed on both sides, and the cap stone be reset and repointed. The outer side of the walls should be repointed down to the brick band course. As with the lower portion of the structure it recommended that a denser, more moisture resistant mortar be developed for use at these locations that will be less susceptible to future deterioration.

The carpentry and millwork items that require attention are defined as doors, windows, and the cupola. While the structure of the cupola appears to be sound the trim work needs attention. The current millwork for the cupola dates to the 1970's preservation effort and has no historic integrity; this, combined with numerous trim being rotted, open joints at trim where water can penetrate, and the somewhat difficult access for maintenance, leads to the recommendation that the majority of the millwork be removed and replaced, and the entire structure be painted. As for the doors and windows the majority of damage is at the lower levels which have been subject to flooding, moisture, and insect infestation. The main areas of concern being the door frame at the east end of the north elevation, the sash adjacent to this door , and the window sill at the north end of the east elevation. These areas will require the removal and replacement of various millwork components.

It is also recommended that the cut firewood that is stored against the east elevation be moved away from the building, as this provides a good breeding point for wood boring insects. While certain areas may require temporarily removing the item from the building for shop based repairs, some of the repairs may be more readily accomplished in place.

The sheet metal gutters and downspouts have been damaged over the years by severe snow and ice storms. The gutters and down spouts were both constructed of very short sections of lead coated copper which provides the potential for leaks at each joint. While it is assumed that the short sections were used to simulate that which may have been historically correct it does create a maintenance problem. It is recommended that the gutters and downspouts be replaced, and that additional gutter and downspout brackets be fabricated and installed to provide additional support in the event of future heavy snows and ice.

The slate roof appears to be in very good condition. Several slates will need to be replaced and the flashing at the cupola will need to be investigated and corrected when the trim at the base is replaced. When viewing the underneath side of the roof from the interior, the framing and sheathing also appears to be in very good condition; it does not appear that the roof is leaking.

The drawings which are provided as a basis for the recommended repairs are those which were developed for the ca. 1976 repair effort. While the doors and windows are relatively straight forward in their design, the cupola framing may or may not have been constructed as noted on the drawings. Extra care should be taken with this feature when the work is accomplished.

III. BRIEF CHRONOLOGY

III. BRIEF CHRONOLOGY

1848	The engine/guard house of the armory was designed and constructed under the supervision of Major Symington.
1859	John Brown storms the Armory and siezes the Engine House.
1891	Building sold to the John Brown Fort Company, the structure was dismantled and shipped to the Columbian Exposition in Chicago.
1893	Building open to the public at the Columian Exposition in Chicago.
1895	The building was moved to the Murphy farm which overlooked the Shenandoah River near Harpers Ferry. (dimensions of the structure, along with several smaller details were modified during its rebuilding, and the current structure in lower town reflects the changes made at this time)
1910	Trustees of Storer College bought the building from Mr. Murphy for \$900 and had it moved to the college campus.
1958	While at Storer College, the building was recorded by the Historic American Buildings Survey (HABS)
1968	The National Park Service acquires the college campus and the building was moved to its current site in the lower town of Harpers Ferry National Historical Park. It is felt that the block foundation was installed at this time.

Construction documents prepared for repairs to the structure which were to be accomplished by day labor crews under the direction of the National Park Service, Denver Service Center.

John Brown Fort / Flood - Storm Recovery Project / Condition Assessment Report and Preservation Repairs / February 1998

1976

IV. EXISTING CONDITIONS

IV. EXISTING CONDITIONS


General

The current site location of John Brown's Fort is the fourth in its history. The original site is located within several hundred feet, to the north-west, of the current structure and is marked with a small obolisk shaped monument.

The structure itself is brick masonry that is laid in a common bond pattern. Over the various reconstructions, the pattern has been broken and is somewhat inconsistent. The brick work sits on a dressed stone water table. The building falls into the category of Federal style architecture.

Site

While true north would orient the fort towards the short dimensions of the end wall which parallels Shenandoah Street, the last two sets of drawings produced of the



John Brown Fort / Flood- Storm Recovery Project / Condition Assessment Report and Preservation repairs / February 1998

building orients the structures north to the long dimensions such that the main elevation, with all the entrance doors, is now designated as the north elevation of the fort. In order to provide continuity of previous work at this site, this report will keep the buildings north elevation as the long elevation which will also be considered the primary elevation.

The site can be accessed from all compass points with the main route being from Shenandoah Street. The grade from the roadway leading to the point where the Potomac and Shenandoah Rivers meet, on the north side of the structure, is the most accessible for handicapped individuals from a grading standpoint. The interior floor elevation of the building is approximately five to ten inches above the exterior grading and does not provide access under the Uniform Federal Accessibility Stanadards (UFAS) or the Americans with Disabilities Act (ADA). For the most part the grade does slope away from the building on all elevations except on the south. On the south elevation a small depression, directly adjacent to the water table of the building, creates a small swale that allows water from the downspouts to be trapped against the masonry rather than being directed to the lawn area adjacent to this elevation.

North Elevation

The top of the dressed stone water table, at grade level, varies from five to ten inches above the surrounding grade. The mortar joints for the stone have deteriorated over time and for the most part the mortar is non existent. The brick masonry above the water table was laid in a common bond pattern, but the header courses vary from every seventh to eighth course, and in some areas there are no header courses but just running bond. The damage to the lower fifteen courses of brick focuses around the deteriorated mortar and can be attributed to the severe flooding that has inundated the building over the last several years, and to a possible rising damp situation.


This elevation proper can be broken into three bays, each designated by a brick arch outlined by a soldier course of brick. The upper portion of each bay is infilled with a semi-circular window sash from the spring line of the arch, and a door from the spring line to the ground. The elevation measures approximately 34'-3" in length with each masonry opening measuring approximately 8'-0" wide; this leaves the brick piers at the corners and between bays at 2'-6". The pair of double-sheave doors in the center (D102) and western (D103) bays are similar in design and construction; they are 1" thick (actual) vertical tongue and groove board on the exterior and 1' thick (actual) diagonal tongue and groove on the interior. The door on the eastern end of this elevation (D101) is also constructed of tongue and groove boards but it is a single double-sheave door that

measures 3'-10" by 8'-3" and it is centered between two glass side lights which are approximately 1'-10" by 5'- 0"; the bottom portions of the side lights being a flush wood panel. While the large pair of double doors have minimal damage at the bottom portions of each leaf, the single door and frame with its associated side lights has seen more drastic decay from both moisture and insect infestation. It should be noted that the interface between all of the door and window frames and the masonry openings are/were filled in with mortar which has failed and allowed moisture to get behind the frames and rot the wood out from behind. Another issue that was noted is the glazing at the window sash; over the years the glazing compound between the glass and the wood has become brittle and cracked; this creates another place for water intrusion and eventual decay of the window components. It appeared that approximately 50% of the glazing compound is in this condition.

South Elevation

The south elevation is a mirror image of the north except that the lower portions of each bay do not have doors but are filled with recessed brick masonry. The same issues exist relative to the masonry. The mortar at the joints in the stone water table is missing and the fifteen courses of brick masonry above the water table have extremely soft mortar joints that can be attributed to high water levels during flooding events and possibly rising damp. In addition to the soft mortar the lower five courses of brick have moss and lichen growth which is contributing to the deterioration of both brick and mortar.

The semi-circular window sash at each bay are divided into four sections (see diagram), and as on the north elevation approximately 50% of the glazing compound has become brittle and cracked which will lead to future deterioration of the window components if not corrected. The only rot noticed on these windows was at the western



John Brown Fort / Flood - Storm Recovery Project / Condition Assessment Report and Preservation Repairs / February 1998

end of the eastern window (W108), the bottom rail at this end needs to be replaced. It was also interesting to note that the wood sills for these windows (WT106,WT107,WT108), which appear to be replacements (ca. 1976), do not have a drip edge cut into the underneath side which would help to keep water from running back under the sill and to the building.

East Elevation

The east elevation measures 22'-3" in length, and is divided into two bays. An inswinging casement window is located in the center of each recessed bay. The windows are divided into two sash with each sash having twelve lights which are 9/11. The window sill on the north end (W110) has a combination of rot and insect damage at the right end. The end returns of both window sills have separated from the brick and have left gaps for water to penetrate into the end grain and accelerate deterioration and rotting. The window on the south end (W109) has rotted at the bottom rail and it is suspected that the rot has also effected the bottom of the side rails and the pins holding the sash together. The pins holding the bottom and side rails together on the north window are also loose ; a closer look at this sash may also reveal deterioration that will require additional replacement. As was also noted on the window sills of the south elevation, the sills do not have a drip edge cut into the underneath side which would help prevent water from rolling under the sills and to the wall.

This elevation had a stack of cut wood piled 1-1/2'-2' high adjacent to the masonry. This does not allow for the masonry to dry out properly and is a breeding ground for wood boring insects.

The mortar joints of the stone water table have deteriorated as have the fifteen course of brick masonry above the water table. Here again water from past flooding has taken its toll. The end walls of this elevation extend up above the roof line and form a crenelated gable wall that is capped by stone. The corbeled brick at the eave line of the north and south elevation carry around this elevation in a brick band which falls about four courses above the brick arches. The area above the band to the stone cap acts , for the most part, as a parapet wall and the mortar is in very poor condition. The joints for the stone cap are also in poor condition, and the cap stone itself may need to be removed and reset.

West Elevation

The west elevation mirrors the east except for the window configuration. The windows in the two bays on this elevation are the semi-circular ones that are typical of those found on the north and south elevations with a blank recessed brick panel below.

The deteriorated joints in the stone water table, and the ten-fifteen courses of brick masonry above the water table are similar to those found at all the other elevations. The lower two to three courses of brick have moss and lichen growth that allows for excessive moisture to be trapped within the soft brick. A marble marker located in the pilaster to the north side of this elevation shows signs of minor vandalisim with a mark of "H". The four iron pins holding the slab in place have started to rust and are just beginning to stain the stone. The crenelated gable wall shows the same signs of deterioration as the east elevation, and is in poor condition. The cap stone joints are also in poor condition, and here again, the stone may need to be removed and reset.

The wood sash in both bays appears to be in good condition except for one piece of glass that is broken on the north window (WT104). The glazing compound around the glass is cracked and brittle on approximately 50% of both windows (WT104/WT105).

Roof and Cupola

The roof is covered with slate and is a uniform 9" width with an exposure of 6" - 6-1/2" to the weather. Due to the uniform gray coloration it is possible that the source of the slate may be from the Buckingham-Virginia Slate Corporation in Arvonia, Virginia. The schedule of their standard roofing sizes indicates that with a 6 1/2" exposure and a 9" width, the length of the slate would be 16". The standard thickness of 3/16" also conforms to that which is on the building. The ridge is overlapped to the north approximately 2". There are several broken or split slate but the overall condition of this roof is very good.


The gutters and downspouts are located on the eave lines of the north and south elevations. The lead coated copper gutter is a half round that is 6" wide that was fabricated in short sections of 1'-8" and soldered together. The high point of the gutter is at the center of the building and slopes down to both east and west ends to a 3" diameter lead coated copper downspout. The gutter is supported by nine mild steel gutter pins that are driven into the brick joints at the corbeled eave line. The gutter itself is quite wavy but it appears that it is sloped properly. It was not water tested so it is unclear as to the water tightness of the joints. The downspout is also constructed in short sections of 2'-4"

and is also quite wavy; three straps hold the gutter tight against the structure with a wood block at the base to hold it out from the water table.

The woodwork on the cupola shows the most signs of distress. The most noticable locations for rot are highlighted with a black fungal mold; this includes the crenelated trim at the upper roof and the railings at the lower portion of the cupola. At some point in the last twenty years it appears that the 1" x trim boards which cover the corner posts were cut approximately 2' above the metal deck and replaced on all four columns. The joints have opened up and it now presents a place for water to be caught. The trim at the top of the column on the south east corner was either built with a slight slope or it has settled. The joints on the majority of trim have opened and allow for moisture penetration and eventual rot. The flat seam roof at the lower deck appears to be in good condition except for a small separation at one seam towards the center. The upper roof could not be accessed with the lift and was not investigated at this time. The tongue and groove siding that forms the base of the cupola is rotting through at the bottom boards that are adjacent to the roof surface; it appears that there may not be enough space between the roof slate and the bottom boards and when snow and ice builds up at this point it gets trapped and wicks into the wood. It will also be necessary to look at the flashing details at this area to ensure that it is properly flashed.

Interior

The structure is divided into two rooms on the interior, with the dividing wall between the spaces being constructed of brick. The two bays containing the pairs of doors open into the larger space while the smaller space, on the east end, is accessed through the single door with the sidelights.



John Brown Fort / Flood - Storm Recovery Project / Condition Assessment Report and Preservation Repairs / February 1998

The floor in both areas is brick, laid in a basket weave pattern, in what appears to be a sand setting bed.

The wood members of the roof structure are exposed to the space below and appear to be in very good condition. The slight green tint to the members implies that the wood maybe pressure treated. There was no obvious signs of any roof leaks.

The two pairs of doors into the large space are missing small diagonal pieces at the base of the doors. The wood nailing block on the west end of the brick pier to the center bay has pulled away from the masonry. The single door and sidelights have not withstood the flooding and insect infestation as well, and the lower portion of the door and frames are in poor condition, as are portions of the frame and stops for the sidelights.

V. PRESERVATION TREATMENT RECOMMENDATIONS

V. PRESERVATION TREATMENT RECOMMENDATIONS

Site

Provide universal access at the north elevation entry. Minor regrading and the addition of five to ten inches of additional fill can be installed to provide an earthen "ramp" to entry level by raising the ground level. This will also provide additional positive drainage at the north elevation of the building. A slope of between 1:10 and 1:12 is recommended by CABO/ANSI A117.1-1992; accessible and usable buildings and facilities; (a slope of 1:6 is permissable for a run up to 2 feet). Regrade to acheive the lowest possible slope, a 1:12 to 1:20 is the preferable range for exterior grading. see preservation brief # 36.

Site drainage will be improved with minor regrading at all elevations to create positive drainage. Other options for improving site drainage include extending the downspout ground leaders so the discharge is more than 18" from the base of the building.

Masonry

The dressed stone water table, at grade level, should be excavated to the bottom of the stone and the joints raked out and repointed. The 1976 construction drawings indicate that the water table was built on top of a concrete block foundation wall that should be just below the existing grade level. The stone itself appears to be approximately one foot in depth and the existing grade should be approximately 6" to 1'-0" above the bottom of the stone.

The first fifteen courses of brick should have the mortar joints raked out and repointed around the entire perimeter of all the walls both on the interior and the exterior. The soft mortar can be easily removed by hand tools. It is recommended that the replacement mortar be a mix that is more water resistent than the existing material.

The brick joints on the east and west end walls should be raked out and repointed from the brick band to the stone cap on the exterior and from the roof line to the stone cap on the interior. Here again it is recommended, that since this area is more susceptable to freeze thaw cycles, that a more durable mortar mix be utilized than what is currently in place.

The stone forming the cap of the walls on the east and west elevations should be removed and reset. It is also recommended that the center chimney feature on these elevations be provided with a mortar wash that is slightly sloped, as not to be seen from the ground, to help facilitate water run off at these areas. Another approach would be to cap the chimneys with a sheet metal hood.

The marble inset on the north end of the west elevation should be cleaned of the rust stains that are forming due to the erosion of the steel pins that help to keep it in place. A poltice may need to be used to lift the graffitti stain. The steel pins should be removed and replaced with a non staining material such as stainless steel.

Windows

The semi-circular windows on the north, south, and west elevations are for the most part in good condition. While only two broken panes of glass need to be replaced, one the west elevation (WT104) and one on the north (WT102), the glazing compound for a large percentage of the windows is beginning to crack and peel. While this may not present an immediate problem, it is recommended that while the other work on the structure is being accomplished the deteriorated compound be removed and replaced to ensure long term durability of the window components.

It is estimated that this repair work is needed over 30% - 40% of the existing window area. The western most half of the bottom rail at the east window on the south elevation (WT108) is rotted and needs repair. If this cannot be removed easily, it is recommended that epoxy repairs be done in place. A similar condition exists on the two end bottom rails of the center window on the north elevation (WT102); this may also be a window to repair in place. It is also recommended that the wood sills of all semi-circular windows on the south and west elevations have a drip edge cut into the underneath side of the sill (kerf cut).

The casement windows on the east elevation (W109/W110) should both be removed and repaired . The most serious work is the replacement of the wood sill on the north end of this elevation. The sash itself , on both windows, needs repair to the bottom rails, and all pin joints should be verified and reglued or replaced as necessary. As with the semi-circular windows , the casement window sills need to have a drip edge cut on the underneath side. It is also recommended that approximately 30% of the window panes be reset with new glazing compound.

The interface between the wood frames and trim on the windows and the brick masonry were filled with mortar. While some of the mortar has withstood the test of time, a number of areas have failed allowing water to penetrate behind the trim to the frame. A decision needs to be made as to the benefit of replacing these intersecting planes with a sealant rather than mortar.

Doors

The two pairs of double sheave doors at the center (D102) and west (D103) bays are in relatively good condition. The center doors are missing two small diagonal boards at the lower corners where the doors intersect when in a closed position. It is recommended that these boards be replaced. While not noted on the field notes it would be wise to run some additional material for similar replacement on the other door. A nailing block , which is located the left hand side of the interior, for this center door, has pulled loose from the brick and needs to be reset. The left hand leaf of the door will need to be removed to relieve the pressure on the frame while this work is accomplished.

The single door (D101) and sidelights (DSL1/DSL2) are in poor condition. It is recommended that the entire unit be removed for repairs. This recommendation is based on the fact that the

frame on the east end of this opening is rotted up to a height of 8'-2" and repairs need to be made to the door frame, door, flat panels below the lights, the bottom rails of the sidelights, and the window stops.

Roof

The slate roof is in very good condition. It appears that there are less than a dozen broken slate that will need to be replaced. It is recommended that the broken slate be removed and replaced. Further investigation is necessary to determine the flashing details at the intersection of the slate roof and the base of the cupola. The flat metal seam roof that covers the cupola could not be accessed but if the floor deck of the cupola is an indicator of condition, it is probably in good condition. The flat metal seam roof that covers the floor deck may have one small seam in the center that needs to be cleaned and resoldered.

It is recommended that the 6" half round gutters on both the north and south elevations be replaced with lead coated copper that is fabricated in longer sections. It is also recommended that additional gutter brackets be placed on both elevations to provide additional support to the gutter. The 3" diameter downspouts should also be replaced with lead coated copper in longer lengths.

Cupola

The appearance of the cupola, from ground level, would lead one to beleive that this feature is in relatively good condition, but a closer inspection indicates that 75%-80% of the millwork needs to be replaced. The railings on all the elevations need to removed and replaced. The trim boards facing the columns have been repaired and all the joints have opened at the repairs; it is recommended that all of the 1" x trim boards on all four columns be removed and replaced for the full length of the columns. The horizontal siding boards , between the floor and roof, have started to rot at the bottom; it is recommended that all of these boards as well as the corner boards at this area be removed and replaced. The crenelated wood trim at the roof level could not be accessed , but signs of mold on the surface indicates that these features need attention; it is recommended that the crenelated trim boards be removed and replaced.

The only areas of the cupola that do not appear to need attention are the decorative brackets, the cornice they are attached to, and the underneath side of the roof. It is assumed that the structure of the cupola will be in good condition when the trim is removed but this will need to be verified when the work is being accomplished. The other area of concern that needs to be investigated , when the trim boards on the columns are being removed, is the top of the south-west column , which appears to be tilting inward. A decision on what is causing the problem and a recommendation will need to be determined in the field.

VI. PRIORITIZED TREATMENT RECOMMENDATIONS

VI. PRIORITIZED TREATMENT RECOMMENDATIONS / WORK TASK LIST

1. Doors and Windows (including painting)

- A.) D101, DSL1, and DSL2 : remove door, sidelight and frame; replace all deteriorated wood and replace.
- B.) Windows at east elevation, W109 and W110, remove sash and repair, remove and replace sill on W110.
- C.) Windows at north elevation, WT101, WT102 and WT103.
- D.) Windows at south and west elevations.
- E.) Doors D102 and D103.
- 2. Masonry
 - A.) Rake and repoint stone water table.
 - B.) Rake and repoint brick.
 - 1.) Base repairs.
 - 2.) Gable end parapet repairs (includes stone coping).
 - 3.) All other repairs (chimney, marble inset).

3. Site Work

- A.) Regrade at north elevation to provide accessibility.
- B.) Regrade at south elevation to create positive drainage.
- C.) Regrade at east and west elevations to create positive drainage.

4. Millwork at Cupola

A.) Remove and replace all deteriorated millwork (includes painting).

5. Roof Repairs

- A.) Remove and repair broken slate.
- B.) Flashing (cupola).
- C.) Remove and replace gutters and downspouts.
- D.) Joint Sealers
- E.) Gutter Hangers

VII. BUDGET ESTIMATE

SUMMARY OF COSTS

	ITEM	TOTAL COST
Div. 1:	General Requirements	\$12, 525.00
Div. 2:	Site Work	\$1,700.00
Div. 3:	Concrete	not used
Div. 4:	Masonry	\$8,070.00
Div . 5:	Metals	\$2,300.00
Div. 6:	Wood and Plastic	\$5,300.00
Div. 7:	Thermal and Moisture Protection	\$3,700.00
Div. 8:	Doors and Windows	\$11,700.00
Div. 9:	Finishes	\$1,900.00
Div. 10:	Specialties	not used
Div. 11:	Equipment	not used
Div. 12:	Furnishings	not used
Div. 13:	Special Construction	not used
Div. 14:	Conveying	not used
Div. 15:	Mechanical	not used
Div. 16:	Electrical	not used
Grand Total Div. 1 - 16		\$47,195.00

CLASSS "B" COST ESTIMATE

item	qty.	mat.	labor	total
Div. 1/General Provisions				
Supervision	L.S.		6,000.	6,000.
Supplies	L.S.	1,500.		1,500.
Equipment	L.S.	1,500.		1,500.
Transportation	L.S.	1,725.		1,725.
Project Record of Treatment	L.S.		1,800.	1,800.
total				\$12,525.
Div. 2/Site Work		- 		
Trench at water table	3 C.Y.		800.	800.
Regrade	6 C.Y.	50/C.Y.	1,200.	1,500.
Sod	100 S.F	2/S.F.	200.	400.
total				\$1,700.
Div.4/Masonry				
Rake and repoint brick	1,200 S.F.	250.	5,800.	6,050.
Rake and repoint stone	200 S.F.	10.	400.	410.
Remove and reset capstones	40 L.F.	10.	1,600.	1,610.
total				\$8,070.
Div. 5/Metals				
Gutter pins	18EA.	1,800.	500.	2,300.
total				\$2,300.
Div. 6/Wood and Plastic				
Millwork at cupola	L.S.	2,500.	2,800.	5,300.
total	·······			\$5,300.

item	qty.	mat.	labor	total
Div. 7/Thermal moisture protection				
Repair slate roof	12 EA.	200.	400.	600.
Flashing	L.S.	250.	800.	1,050.
Joint sealers	100 L.F.	.50	200.	250.
Gutters and downspouts	128 L.F.	1,200.	600.	1,800.
total				\$3,700.
Div. 8/Doors and windows				
Repair doors	L.S.	500.	3,200.	3,700.
Repair windows	L.S.	500.	3,000.	3,500.
Glazing	L.S.	500.	4,000.	4,500.
total				\$11,700.
Div. 9/Finishes				
Painting	L.S.	400.	1,500.	1,900.
total				\$1,900.
GRAND TOTAL				\$47,195.

VIII. PHOTOGRAPHS (NOV. 1997)




Figure 1 - John Brown's Fort, north elevation.




Figure 2 - John Brown's Fort, south elevation.




Figure 3 - John Brown's Fort, east elevation.

32




Figure 5 - John Brown's Fort , dressed stone water table at north elevation. Note deteriorated mortar joints.




Figure 6 - John Brown's Fort, double sheave doors at center bay of north elevation.



Figure 7 - John Brown's Fort , typical detail of bottom rail at semi-circular window



Figure 8 - John Brown's Fort, rot at window sill of northern most window at east elevation.




Figure 9 - John Brown's Fort, door and sidelights at eastern bay of north elevation. Note gutter discharges at base of building.




Figure 10 - John Brown's Fort , detail at bottom of door and sidelight showing rot.



Figure 11 - John Brown's Fort, wood jamb of double doors at center bay. Note gap between wood and masonry.




Figure 12 - John Brown's Fort , interior elevation of jamb at center bay doors. Note wood nailing block pulling away from masonry.



Figure 13 - John Brown's Fort, interior of east end wall above roof. Note stone caps and lack of mortar wash on chimney features.



Figure 14 - John Brown's Fort, interior view of south-west corner of end wall. Note deteriorated mortar joints.



Figure 15 - John Brown's Fort , roof as viewed from south looking northeast. Note cap slate overhangs to the north.



Figure 16 - John Brown's Fort, plan view of slate roof with one broken slate shown in center. Note trim at base of cupola is tight to slate.




Figure 17 - John Brown's Fort, south elevation of cupola. Note top of column capital at front right slopes inward.




Figure 18 - John Brown's Fort, south elevation of cupola showing crenelated trim boards attached to roof by metal "L" brackets.



Figure 19 - John Brown's Fort , half round gutter on south elevation. Note how shape has flattened out and is wavy.





Figure 20 - John Brown's Fort , detail of gutter hanger and strap.

IX. APPENDIX A / FIELD NOTES

John Brown Fort / Flood - Storm Recovery Project / Condition Assessment Report and Preservation Repairs / February 1998

Park Sheet NATIONAL PARK SERVICE Area WILL MSPORT PRESERVATION TRAINING CENTER of Project Pkg. Checked Feature Date Account FIND , pleskans Phetakas NOTES PPARZEN ONLS? & LAST PLANE Thom -CHECK PADAR FLES MB. W/RS. 1. LARPENTRIT REPAIRS (INCL PAINTING) 2. MARSONET REDAILS 3. ROOF PLEPARES 4. CUPULA(CHANGES DE CUPULA) 1. CARAFINTET PLANKS A. REPAIR TWO LARGES DOOLS (MINOR) B. PROPER PROPERTY ONE SHAMPLOODR (HAJOR) C. PEPPARS TO WINDOWS CORDING USUK (MINOR) D INSDELT ARCHED HEADERS - LOOK OR E PLADINT EXTR WOOD TO MATCH? - HSR? - WHAT 15 COLOR PAED ON 12PR CASEMENT WORG as w/ HINDR DEPARES. 1511 PAPLAZANIPWT + GWOYLO'SILL MARTER SHOULD BE PEPLAZIOS - NO DRIP & UNDLOSIDE > R (TREHEAST: STOLINGOS NEW BOTEH PAILS M maybe dutof may to Atte? anty Mullion 45






Park Sheet 🛆 NATIONAL PARK SERVICE WILLIAMSPORT PRESERVATION TRAINING CENTER Area of Project Pkg. By Checked Feature Date Date Account INTE BAILE FLOOR-とも、 PELATE SONE ANERS SO DODES OPEN PROPERTY (MINOR. Davitte 2000 5- woothe add 1/mge/led by. added drangth? SINCLE DOOD-STRUCT. DAN & thone and NOW; DR denate - possibly repair einsting (neurone and dismonthe) or replace -charled have formite damage 2F. PHENT ELECTORE SILLS ALL ACOUND 48


Sheet 5 Park NATIONAL PARK SERVICE Area WILLIAMSPORT PRESERVATION TRAINING CENTER BEDD of Project Pkg. By Checked Feature Date Date Account ONE CODE corporting who 3. ROOF PERAIRS 9 REPLACE HOPLOD SLATES (30 HAX!) INSPECT IN DETER LOOK 5. RIGE SLATES - WHAT IS PROPER OKTAIL! NALS AND CONFRIED W/ POOFing TAR/STALANT. C. PHPAIR/MAPLACIE FATL GUTTARS- POSSIBLY AND A FEIN HODE HANGERS(PD?) FATIND DUNSPOILS & BASK - HEADADE SO THERE ARE NO PUDDUESCE BLOG. 49


Park Sheet V NATIONAL PARK SERVICE Area WILLIAMSPORT PRESERVATION TRAINING CENTER of BED Project Bv Checked Pka. Feature Account Date Date 1. CUPOLA q. CONDUCT INSPLANON b. PLEPAIR PROVACE DE TUMOPOSTIO WOOD (PAILINGS ADDS) C. PLOLESALAN & AMO YEATTUATON - CURRANTUT NOT NEWTED NOTE-SPELIFT PTG ROT PUSISTENT SPELIES) MILDONICION PRIMER-LOPS of MILDION on NORTH SIDE-ALSO BLOC IS MOSTLY STRADED in WHILDR VENTILATE BASE and ROOF STRUCTURE of WPOLA = ARONIDE AZERSS From INTERIOR? OUDDESADE IS VENTILATED CLUMNS LOOK OR M 1/4 MASE PLATES. ROOF ATENGUNE (HIPPKO) may need belie parted. * oplacement of raile sotrais (4) and upintaries, pour supert notel Hoop and roof-tallelook Hatroancoops for conducin but they lock UK punp & put. 50

.




☆ U.S. GPO:1996-776-865





HARPERS FERRY NATIONAL HISTORICAL PARK JOHN BROWN FORT FIELD NOTES



FIELD NOTES HARPERS FERRY NATIONAL HISTORICAL PARK JOHN BROWN FORT Date: Nov. 10,'97 Inspector: A.G. DONALD/DGC-AR


rage 1

NORTH ELEVATION

· tressed stone water table @ base is 5" to 10" a bare quide utas/ada access would need to ome from the north - area adjacent to bldg. entrances would need to be adjusted to climinate step up to finish flow level on interior o mortar joints @ unter table need to be valued out and reported (3 joints @ ast and could be sound) brick masmy is romning hand with herders that vary from every the surse to every all course (in some cases just running band survive that lack at another is due to nomenous disimatings and reconstructions. · 3° dia. dampists Cerch and with 3 straps holding toursport to wall dam sport appears to be lend coated copper built in 2-4" bectims sections are lossed and crocked. purch maintenance showed up a little after 7:00 q.m. and provided instructions on use of small bucket lift which was set p on the purch elevations. went up to cupo la on conter of voot 1 o the 1×10 (7/3×9/4") frim bards surmiding the four solumns have been cut 25" above the flat seem not and the joint has pulled away all wing water to get into joint . vailing has black motel spores in surface / puble with lente blacked indicates 90% + heads replacement. I • the flat seam (led contred copper not/13/2" inde ponels/ looks relatively good recommend resoldering joint running east-west @ conter of roof. . tim at the top of the solumns is pulling apart at the conners wood topen is sound

FIELD NOTES HARPERS FERRY NATIONAL HISTORICAL PARK JOHN BROWN FORT Date: Nav. 18,97 Inspector: A.S. Donwo, DSC-AR

NORTH ELEVATION




FIELD NOTES HARPERS FERRY NATIONAL HISTORICAL PARK JOHN BROWN FORT Date: Nov. 18, 97 Inspector: A.S. POWME /DSC.AR

NORTH ELEVATION

· egst toar/uman · termite damage @ left jamb (frame) #18" unde × 8'.2" high × 4'4" think · bottom vail of ast indue votted @ both comers where vil meets stile. o bound & batter toor is rathed @ bottom / toor is vertical undom width x1" thick an exterior and triggonal random width tog (1" thick) on interior ** · jambs @ bottom of tour opining votted (termite termine) vertical bounds 63/8" # 105/8" undre rotted Chase approx 11"+ * from sill simple that panels below wintows facing dow from exterior right panel (on the lower left jumb the word is rotted? the base mide not has started on the lower panel

FIELD NOTES HARPERS FERRY NATIONAL HISTORICAL PARK JOHN BROWN FORT Date: Nov. 18, 97 Inspector: A.S. Downey, DSC-AR



SOUTH ELEVATION

· need to sake at ma report where table stare · slight tepession @ unter table needs to be filled in (required) unter from davansports mains town next to store unter table rother than very thom storetone and not into lown area. . common thank with herder every 7th course . need to chem off muss regention from here 5 courses of brick. a lower 10-15 bick causes have soft martine joints and need to be taked at and repointed. · there are no anip edges at into the wood sills of my of the wood sills of my of the o the western most bottom vail of the eastern window is water and needs to be verticed. ionit high spot in middle with solar ionit high spot in middle with slope in afters 2 east quest entes 1 sports , 6° gutter lis in 20" sec for gutter drumsprits are 3" tig lead contra appart in 2-4" + langth = 3 hash half elevation of holding down sports in place,

FIELD NOTES HARPERS FERRY NATIONAL HISTORICAL PARK JOHN BROWN FORT Date: Nav. 18, 97 Inspector: A.S. Dave Dx.AR

EAST ELEVATION

.

0

0

o wood is stached up approx 2't high along artime cleartin / this feads I milt potential blocking to damp maximy Mace 4 mites · the undre a the with and has termite hot daminge on the sill the interface between the wood sill and the birch is gan and to the and quinh at the shold be called to prevent water getting 6 · argest require 6-12 panes of 1439 his ist on the lottom will of the · the window on the and soft right such /anticipate that joints may be cotted . The wood pins on the north and window such are pulling at mataring a problem le the lower joints (i.e. bottom vail & stiles) mismy from mich bout hed nt above arches/to to heers to be mt jeponted brick massing 15= courses from stone water table needs to be taked at and reported.

FIELD NOTES HARPERS FERRY NATIONAL HISTORICAL PARK JOHN BROWN FORT Date: Nov. 18, 97 Inspector: A.S. Darken / DSC.AR · WEST ELEVATION second pane of from x11 on 1918 stone (mark H) needs to be knowed gloss need to paffifi Jook 2 remains 4 steel pins helding stone in place metal starting to wat and staining stone. masmin from brick leant 3 courses are indue arch) to top needs to be when but and reported. need to clean moss off laver 2.3 cruses of birch just dove voter table stone , need to whe at and repoint joints Quarter table stone · 10-15 causes of brick above unter table need to be valed at and repoints replace I broken window pane 2 such side of with impore. * second pane up from bottom rail

FIELD NOTES HARPERS FERRY NATIONAL HISTORICAL PARK JOHN BROWN FORT Date:


Inspector:

INTERIOR

s voof sheithing from interior looks very good the to greenish alor suspect can treated wood used in 1970's mare. · also bobs like pressen freited sill plates used for roof reffers . brick flow hild in broket wave pattern · cast side of interior used for inter storage of unifinals minimal to no program troppings spider webs minimal interior very chem
 window stops 2 side wondows need to be replaced 1/2" × 2/2" rotted/
 termite dramage


X. APPENDIX B / DRAWINGS

John Brown Fort / Flood - Storm Recovery Project / Condition Assessment Report and Preservation Repairs / February 1998



-RECONSTRUCT CHOLA PARTIAL RESTORATION 4444 RECONSTRUCT CUPCLA TO REPLACE ALL ROTTED ROOF FRAMING MEMBERS SEE FRAMING PLAN SHEET = 4 REPLACE ALL (4) RED SANESTONE CAPS TO MATCH DETAILS OF ORIGINAL P REMOVE EXISTING CUPOLA Base (Steps. Reconstruct Cupola to Detail **A** _ REFAIR SASH AS REQUIRED ALL INTERIOR WALLS REUSE CRISINAL HARDWARE WITH BRICK FORT CTRATE PROPERTY BRCK IN MTEROR DOORWAY TO MATCH EXISTING BRICKWORK IN COURSING AND JOINTING, TOOTH ALL NEW WORK INTO SXIATING IN JODOR 10 HAYS CONTINGUS COURSING EXIST BLOCK POUNDATION BY NOS TO REMAIN **BROWN'S** SECTION A-A SECTION 8-B · 4 - I - M 1/4" = 1-0" 2 1/4 . 1- 0' SCALE : SCALE: NHON 94'- 1 ANEW COPPER GUITER & Down Sports SECTIONS NEW LATE ROOF ENGINE ROOM REFAR WINDOW FRAMES RECONSTRUCT CUPOLA FILL AN DE WAR RESET FORTION OF BROCK FLOORING AND REFACK ALL JOINTS WITH SAND SCALE NONT Ø GUARD RN. ANS PRESENT ENTRANCH DOORS ARE TO BE FETAINED. ALL NEW HARDWARE TO BE REPLACED WITH ORGINAL HARDWARE IN STORAGE. ٦ LANA JUTTER PREPARED PREPARED ETITIATS V. L. BANLOW U. L. BANLOW DATE THE CALL OF COMMINISTICS PREPARED PR PLAN . 2 ROOF . PLAN · FLOOR · 1/4" = 1' - 0" SCALE: 1/4 . 1 - 0 2 BCALE: Befracher abet profit all disservang and febr mer prayservening of the enk aber baker bermehring and inter or any even at Bernauty.

.





--- *


3/10/ 11-14 0'-11/2 9'-7% -B'X9'XH ANGLE. 24 LONG 2- 8 296 x4 PLATES OF TRUSS # 3 OF TRUSS #4 OF TRUSS #2 OF TRUSS !! PARTIAL RESTORATION PEPLACE KAFTERS Rotted & Droken A3 Required HOLES FOR % BREQUIRED THE THICK LESS HEN ANG PURLIN ------NEW C'XE FRAMS SOT ON BOTTOM CHORNES & CAS ~ HEEL CONNECTIONS REPLACE ROOF SHEATHING AS REQUIRED. STEEL ISOMETRIC . DRAWING REMOVE REMAINING CUPOLA BAJE & JIEPS AND RECONSTRUCT CUPOLA FRANING D L CETAILS SEE SHT DG11. 0-1 5 x 5 x 4 STEEL ANGE 24 LONG 78 × 9" op chord, FORT STIOM CHORE BX OF XA PLATES TRUSS CORDS **BROWN'S** ŃΨ ൭ an BRICK WALL STEEL HEEL CONNECTION đ REUSE EXISTING BOLTS NHON SEE SH. A B FOR CUPULA FRAMINO HO BEICK WALL -MллA ROOF · FRAMING · PLAN · HAT CUPOLA FRAMING DETAIL OF TRUSS HEEL 3/0 + 1' - 0* 4 SCALE: INTO A S'A HE SLOT BCALE = 3" = " - 0" 65×65 COLA OF 2o 2×4 RAPTING D 18 & ្នត៍ ON TRUSS #2 FRAMING Distantion of NEW SLATE ROOP KING ×3/4 AKGO PURLIS NEW CAPPER GUITERS Ö iI. Top chong Ki P ROOF STRUT HANDE Dig x 14 ON BOTTOM CHOED OF TRUSS ÷۳ 1050 WIN DEAM SET ON DOTTOM LUADO ALUASES #2 AND #9 GATTON CHORD IS HEAD BOAT KOOF TRUSS E KAOF TRUSS # 5 REUSE ALL EXISTING HARDWARE USED ON THOUSES. KG. 60 BOTTOM TRUSS SECTION . DRAWING NO. CORDS ROOF · TRUSS 28,008 CHECK ALL TRUSSES FOR ROT WITH WALL POCKETS 3/4 . 1-0 R.L. BARLON DESIGNED SCALE: **(**4) Y4 + 1'-0" SCALE: NOTE: DISMANTLE THE EXISTING TRUSSES WITH CARE. EXAMINE TRUSS JOINTS. OBSERVE METHODS OF DOWEUNG AND FASTENING. THE ARCHITCET SHALL DE PRESENT AT THISTIME, AND WILL DETERMINE IF ANY REVISIONS TO DRAWINGS SHOWN ABOVE, TO TRUSS CONNECTIONS, AND FASTENING DETAILS, BE NECESSARY. W.L. BARLOW PK4 94217 NOTE: ALL DEMENSIONS GIVEN ARE Berligfigt (4.2) Brit mei it Dourien og – t Blutte it gi CHECKES CHECKES NOV. 1874 ACTURAL. 4 e fa cale a 0 13


1


and the second secon













a Alexandra a state of the



ŝ,



 Natis: Het dipped galvanized or alwainum, of sufficient length and holding power, as recommended by the shingle manufacturer.

 Lead Costed Copper (For use in flashing): Cold rolled copper, meeting require- us of ASTE B370, costed on both sides with not less than 8 pounds per 100 square foot a accordance with ASTE 0 101, Type 1, Class A.

EXECUTION:

Stating:

1. The ontife surface of all facts, unless otherwise specified, and all other surfaces as indicated on the drawings, shall be covered with slate as herein specified, in a proper and exterlight sammer.

2. The slote shall project $1\frac{1}{3}$ and each course shall be shall be take in merizontal is set of the black bypesure, and each course shall break joints ofthe the preceding one to the transit be doubled using some thick-acts slate for under-eave slote to be approximately a inchest longer them exposures of first course.

 States everlapping sheet metal each shall have the natis so placed as to avoid turing the sheet metal. Exposed noils shall be permissible only in top courses to maxeldable.

4. Heating fit slote stound all vertisal surfaces.

9. Nalls shall not be driven so far as to produce a strain on the slats.

9. Cover all apposed nail heads with elastic coment, ridge states shall be laid in elastic coment spraod thickly over unopposed surface al under courses of state, nation securely in place and carefully pointed with elastic coment.

7. Build in and place all flashing places.

8. Upon completion, oil sinto must be sound, whole, clean, and the root shall be first extertight and heat in every respect, and subject to the Contracting Officer's approval.

Rooting Folt:

1. On all surfaces to be covered with state, lay felt in norizontal layers with yoints lapped towards the saves at least 2 inches and well secured along laps and at ends as mecessary to properly hold the felt in place and protect the structure until energing the test shall be preserved unproken, tight, and whole.

2. Folt shall lay all ridges at least 12 inches to form deuble thicknoss and shall lapped 2 inches over motal flashing.

....

BENTRAL

Sumples: The 12-inch by 12-inch samples of each sheet metal material. Shee pattern, ISR, color, and thickness.

8. Jes Conditions:

1. Determine that surfates are smooth and dison to estent required for sheet metal x. Correct or report defective surfaces to the Contracting Officer. Verify regists, is, and surfaces to receive sheet betof are installed and free of intrusions.

Selece community work, weitly shapes and dimensions of surface to be covered.
 Se not segim mark until surface construction, including all projections, is installed.

ERIALS

Inset Netal: Loss conted copper. ASTN Dig1, Type 1, Class A, soft or Nord tomper, copper sheats, dold raited, saight 24 ounces per square test. Esclusive of losd costing.

Festeners: Sorous. FS FF-S-107, soll-topping shoet motal type, or equal. ICUTION

A. Instelletion.

.

1. General: Install work extertiont, eitheut eaves, warps, buckles, fastening resses or distortion, allowing for expension and contraction. Nom exposed odges; gie bottem edges of exposed vertical surfaces to form origs.

2. Regists: install in accurate incetions, straight, in-line, and with leak proof joints.

3. Solvering: Clean and flux metals prior to soldering; see solder completely rough seem width.

4. Rost Countertlashing: Overlap base flashing 4 inches minimum. Install bottom edge tight spainat base flashing; tap soon vertical joints 3 inches minimum; apply right. Biter, hap seam, and close corner joints with solder or sestant.

5. Base fiasning: Extend flashing from 2 inches poore top edge of same shingle 1-Y inches above butt edge of covering edge of shingle. Extend up vertical surface 5 inches ainteum and enter rooting 4 inches ainteum. Install flashing under each shingle course; secure top edge of flashing by neifing to substrate. At chimeys, of hatches, and shylights, extend up vertical surface 6 inches ainteum and ento sting 4 inches pinimum. Solder top vertical seams; miter and solder lap corners.

SUTTERS AND DOWNSPOUTS

1. GENERAL

A. The work of this section consists of installing gutters and deenspouts of a Ristoric dusign.

8. See Section 05781, Brought Iron-18th Century for related work.

2. HATERIALS

A. Butters and deenspouts to be copper cold rolled, sheet, 24 ounces per square foot. Longth of gutter sections, $14^{\ast}{}^{\ast},$

- 8. Vesners Neoprene.
- C. Fiss for copper: Approved commercial brand, No acid.
- 8. Solder for coppur: ASTE 832. Se percent land and 50 percent block tim.

E. Leader Road streens: 14 gage copper vire mesh, ½" by ½", installed pur

drawings.

9. EXECUTION

A. Installation: In accordance with menufacturer's instructions and recommendations and Smacks architectural sheet metal specifications, hangers and fasteners, spaced as shewn on drawings. Support and anchor each unit as shewn with lines and grades accurate and true in alignment and lecation.

B. Soldering: Wire brush surfaces to be soldered. Use well heated coppers to heat sheet and seest completely through full electh of sees. Seem shall shee a minimum of f inch of evenly flowed solder. Solder in flat position when possible. Seems on slopes steeper than 45 degrees, solder a socend tree.

C. Neaprone washers: To be installed so that none of the mild steel gutter practets, downspout brackets come in contact with copper.

FINISH MARDUARE

1. BENERAL

A. All current hardware used on the building is to be removed and replaced with the originals non in storage and reproductions of missing hardware.

8. Final hardware soluction will be made by the architect.

2. MATERIALS

 Historic cast iron strap hingles and pintles now in Storage by the park will be used on all dears.

 3" cast iron butt hingles will be used on both casement windows in the Guard Room. (Four pair required).

C. Frem boits for Buard Room windows; 1'' X 4'' with keeps; type #4. Manufactured by Ball & Ball, 483 W. Lincoln Hwy. Exten, Pa. 19341 (Eight required).

D. Boor boits fof Engind. Ruowidoors to be X-607-6 with #3 type kusper, 10" X 1 3/4" (four required).

E. Boor hasps required for the Guard Moom door and the Engine Room doors will be reproduced for mild steel to imitate cost iron. Busign will be selected by the project prohitest.

3. EXECUTION

Install all hardware as directed by project supervisor.

SEALANTS

1 AFMFALL

A. Description: The eark of this section consists of providing secients around exterior aponings.


8. Quality Assurance: Standards, Faderal Specifications (FS) and manufacturors' printed recommendations.

2. BATERIALS

SEALANT: FS TT-S-227, Type 11, and FS TT-S-220, Type 11. Synthacalk GC-0, and part polysuifide base synthetic rubber or Synthacalk GC-8, two part polysuifide base synthetic rubber, manufactured by Pocore Chomical Corporation, 300-400 Mest Sudgiey Avenue, Philadelphia, Pennsylvania 10140, or approved equal. Colors shell match adjacent materials, as approved.

3. EXECUTION

3-1 Application: In joints, apply with hand coulding of air pressure gun using proper size multiple. Joints up to 1/2 inch wide, depth, some as width. In joints 1/2 inch and wider, dupth, 1/2 inch winnows. Tool joint surface to compress compound into joint insurface, to possed and a watering to the constant and even.



PARTIA

MASONRY RESTORATION

I AS DE BAL

A. Description; The work of this section consists of closing in the present mesonity opening between the guard and engine repair, the repair of brick eround the restored trusses and repeinting of the interior valis.

8. Product handling: Store portor paterials in a dry place under cover to prevent denigs, permitting all elfeulation.

9 MATERIA: 0

A. Misterie prich: Sound, hard, no chips with true adges. Match existing in size, saspe, and general appearance.

9. Mortar; I measure of white pertiand coment; 141/2 measure of high plasticity lime; 7 messures of easied sand, mutch eater of stisting.

1. EXECUTION

1. Proparation of interior unlis: Remove foreign material, loose mertar, and stone; rake cc^{\ast} all joints to bound surface; flush raked out joints and voids with olean mater shall stand it remayed.

8. Bixing morter for pointing: Maten existing morter by taking an unseathured sample from a joint within existing sail. Estestism the solar from the aggregate used. Bix sit materials by volume, dry as can be handled; in a secondical mixer until theroughly com-... eined. Just prior to pointing, als two be annoted, in a decentral biler entit thereugh y com-eined. Just prior to pointing, als into the dry als enty eneugh stor 1d doke mertar eerkable. Use mertar sithin 20 minutes after adding woter. Tomperature is 80 degrees f. use mithin 2 hours; discard any remaining portar. Actempering eithin these limits will be practited only as necessary to maintain perkability. Use no estelum admixtures or definition and enty antifreeze chemicais.

C. Pointing prick joints: Roughon surface of joints for ponding of non meterial to existing. Apply morter, motted slightly, into the joint under sufficient pressure to assure a solid joint. Brick joints to an tealed as shown on drawings.

TROUGHT IRON - LATA CENTURY

1. GEMERAL

A. Hild steel items used to simulate 19th century prought iron park shall be quality staduced and approved.

8. Fabricate all mild studi items as our full size details

C. Prior to beginning construction, submit samples of mild steel items. Samples mild as foturned for use in work.

A. Mild stool: Low carbon, general purpose, merchant quality, suitable for forming and walding, complying with A121 M-1020 for not rolled bars. Bonderized, tracted with phosphoric sold and proper actalyst not exceeding 100 mg per square foot, providing a fust resistant base for paints, \$2PC SPS

Paint, Rust-Clove X-80 Red Primar and Rust-Olove No. 412, Fist Bisck, by Rust-Oleum Corporation, P. S. Sex 32, Evanatan, Hilineis 60204, or approved equal.

3. FIFCUTION

2. MATERIALS

. A. All work, carefully firstarged, indiced, or hommer valded to produce desired design and offact, substantially framed tegather. Free ernaments, solid atid stavi, oarked, inclued, or nammer valded as shown,. Gas er cleetric valding vill hat be permitted

B. Pointing: Cloom all exposed surfaces of rust, sirt, and groase. Apply i seat at primer, and 2 finish coast of flat baint. Pollos conteiner directions and apply paint evening althout runs, segs, halidays, or other defective drusning. CARPENTRY AND BILL POOR

1. MIMBAL

A. Standards: American Institute et Timber Construction (AITG), Architectural Woodvark Institute (AWI), Federal Housing Administration (FMA), and manufacturers' printe fecommendations.

D. Product handling: Store lumber and milleerk, where directed, eff the ground, with protective covers. Be not expose wood to extreme changes of temperature and humidite

2. MATERIALS

A. Road: \$48, free from earpage, stain, ret, or other imperfections affecting strength, durability, and appearance. Heisture content not to exceed 10 percent for yerd fumber and 12 percent for finish fumber. Lumber 2 inches thick and less, kiln dried. for usposed work, nend selected.

Trusses; sli truss members requiring replacement are to be select structural fir er better Douglass fir.

 Framing lumber; al root ratters, cuyota framing to be No. 2 grade, Douglas fir or No. 1 grade, Southern yollow pine. Blocking and furring may be No. 3 or No. 4 Southern yeilen pine.

3. Sheatning: 1 inch Ho 2 or Ho. 3 Southern yollow pins.

Exterior finish. All exposed wood components, C Select or Quality white pine of relies-poplat clear of detects.

Exterior millimork. Door and window frames, sashes, and other millimork.8 and butter or choice shite gine of yotton-poplar clear of defects.

8 Trestment:

I. Lumber specified for exterior use to be Belmanized Brand shall be pressured-logret noted in accordance with the specifications for treatment, of Reppers Company, Inc., with Belman CCA-wood preservative and shall want the trademark PDLMANIZED.

Folmanized pressure-treated tumber shall conform to AVPS Standard LP-2 or LP22 am Beat & Bath Cortifying confermance.

Belannized pressure-treated leasur which is to be printed or verbished shall be klip-dried ur att-sussened to an average moisture content of. 106 or fess before painting. Brush all field auts ofth preservative.

6. Building Penor: 38 pound asphalt saturated fait.

B. Rough Hardwara: Holls, spikes, screes, boits, muts, esskers, anchors, and similar itees of proper size to rigidly secure memors in place. All astarior fastenings, gel-venizes of aluminum.

1. INCOMPANY

A: Layout: Establish elevations; furnish, set, and lay out need framing and dilieert.

8. Fraing: Sizes and spacings as shown.

installation: Cut froming square on gearings, steasly fit; accurately set to rewaired likes and levels; secure rigidly in elece at everings and connectent. De not edt, notch, or borg finaling possess for passage of pipes of senduits without approval Reinforce franing memoers where damaged by cutting.

2. Shins: Be not use shins for leveling on wood or matal bearings. Use slats or this shims with full bearing for leveling on becomy.

1. Batters: Set eith trapp edde pp.

4. Well and Root Shouthing: Nail such based take at each pooring with Se sommen noits driven at a slight mglo. Hoko and joints over bearing and starger joints with no and joint accurring in some space in adjubant boards. Butt boards thugiy to-gathe, and drive nois and betwee surface of board. Then boards are used for bail sheathing, apply them diagonally or use diagonal bracing with norizontally applied thesthing.

6. Finish Carpontry:

1. Trim: Install deer, ernees, and state trim around evenings in single longths miter corners. Install running trim or milleoft in long longths, sith and joints stag-gored over bearings, and at 48 degrees.

2. Notling: Blind noil proce possible. Sive and noil built-up items. On eapered surfaces, set finishing mails to receive patty.

Billwork: Cops motion work at returns and interior angles. Biter at corners 2. Willowins: Gous measures work at returns and interior medies. Witer at corners Shoulder mitur fascia boards. Serioe, miter, and join accurately to detail. Nort backs of eide fist memory. Account back of fist trim memory. Machine sand with grain in shop and finish by hand sanding. Exposed millowing, free from celests. Slightly round geners of square of restinguiar sections. Insure eark all remain in place without and the section of the sections. verping, splitting, or sponing of joints.

4. Exterior Billoork: loowdistely price milloork after installation. Use nonferrous or gaivenized fastunings. If milloork is cut in field for fitting, cast out ends with preservative. Treat milloork after fabrication.

8, . Froms: No bett jeints permitted.

figing: Use converted nations where possible. Revisental siding, long 8 tengths with end joints made at 40 degress enty at beering. Verticat staing, single jungthi. Instalt no siding untit face, sides, fongues and greaves have seen primed. Concested notting, bet notic for patty.

Finish Herdnare and Beatherstripping: fit accurately, apply securaly, and 7. Finish Marshare and Westherstripping: fit assurately, apply Securaty, and edjust exceloity all stams of finish hardware specified. Energies care to avoid marring or injuring adjaeant work or Rardware. Install westherstripping if shem. Set aced thresholds in base seatent compound. He proper boring jos, strike gegs, routers, and templates. Install all leakasts using a system of jos and date equipment tapable of securately outting openings. Belaced scree herds, mared, or impurtee hardware will not be accepticable. Property tog all keys readings and of iver the short hardware contracting officer upon completion of work. In tall items uniferming with fike items in some patition and location.

SLATE SHIMALE ROOF

1. AFMERAL

Standards as established by American Society for Testing and Haterials (ASTH) and menufacturars' printed recommendations, as amended, latest editions, gavern the sert of this testion.

Shingles: Neet requirements of grading rules and application facommendations of National Rooting Contractors Association.

2. MATERIALS

A. Stata:

1. State shall be Genuine Unteding Buckinghem-Virginis Slats as furnished by the Suckingham-Virginia Slate Corporation, 4118 Fitzhugn Ave. Richmond, Vo. 23230, of the following size and thickness. 18-inch long oy S-inch wise by 1-4-inch Bucking-nam-Virginia Brade A Unfading Blue Black Slate Rooting.

2. Att state shall be hard, dense, sound rock, punched for two nails each. Ne oracked slate shall be used. Att exposed corners shall be practically full. He broken corners on ouvered ends which sacrifice nailing strength or the laying of a estertight roof will be allowed.

1615

JOR CONDITIONS

Field Neasurements: Determine exact size of glass by field measurements of items to Pa glazad. Responsibility of glass size rests oith the Contractor. Sizes, if indicated, are approximate, and shall be used for estimate only.

MATERIALS

Stass: Shall be historic as supplied the park and to match existing glass in place.

Sissing Compound: Person 8-242, as monutactured by Person Chomical Corporation or approved equal.

Stating Points: Standard galvanited points.

ELECUTION

3-1 SEMERAL :: Before glozing, check openings to assure they are square, plume, and in we plane. Meintein uniform face and edge clearances.

3-2 PREPARATION: Thoroughly close all surfaces prior to glazing sporations.

1-3 INSTALLATION: Perform all glazing at the site. Wood shall be primed before gizzing. Back putty all giss before setting. Set gisss firsty of a given set giszing ints. Cut excess gutty to signt fine of the mentin leaving a centimuous smooth sloping inform returning meatly at corners. Follow recommendations of fist Gisss Merketing 10CISTION.

3-4 CLEANING AND ACCEPTANCE: After glazing, remove all foreign material left on the tragasnip.

FAINTING AND OTHER FINISHING

1. GENERAL

A. Submit complete fist of meterials proposed to be provided for the work.

8. Proposo at the job site 12-inch by 12-inch somplus of point colors proposed for 1111 Samples shall have paint applied on same surface material as sill be used in the esft.

C. Buliver sealed containers with inbels legible and intest.

8. Store energ directed and protect poterists from damage.

E. Cover and protect finished work of other trades and surfaces not to be painted. a drop cloth: of adaquate size to protect adjacent areas.

Octoraine surfaces to which pointing and other finishing are to be epuli-A are even, smeath, sound, closn, dry, and from from delects affecting proper application. Correct of report defactive surfaces to Contracting Officer.

8. Op not apply finish material when temperature is below 50 degrees F. Bo not ply exterior off based materials in dwap, rainy seather. Bo not apply point on surfaces direct sunlight. Bo not apply finishes in spaces where dust is being generated which veyld speck the finish.

Take necessary processing to keep fire hatafd to a pinious; report from the area ity all ally satts, and other computibles not in covered metal containers.

- WATERIALS

A. Puint and finish Products: Highest quality standard brand, as distributed by a netionally «"even annulabturer. Point products shall be fresh and well ground; shall the readily, cake, or thicken in the container; shall be groken up readily with a ddle to a secon consistency; and shall have any application properties. Other)onting motorials such as finteed oil, turpenting, minoral spirits, missoilaneous thinners, varnish, and shellae shall be the highest quality of an approved manufacturer.

8. Filling Compounds: Use only high quality, nonshrink materials which have been proved. Use putty for need, joint compound for nellboard, jotex and portland seasent or concrete block, and petching platter or specking compound for plaster.

2 Colors: Batch color samples submitted and approved.

9. Beteriels Lest.

1. Exterior Rood: Alkyd, Semi-gloss finish. 1st cost: Aikyd Primur. 2nd cost: Ayd Semi-giess House Paint. 310 cost: Alkye Semi-giess House Paint.

Esturiar forrous motal. Alkyd, sumi-gloss finish, fist coat. Alkyd Loed mate Notal Primor, 2nd coat: Alkyd Protectivo Semi-gloss Enamol, 3rd 4 Silice Chromete Metal Primer. 2nd cost: pat Alkyd Protective somi-gloss Enomet.

3 Exterior galvenized metal: AikyJ, sumi-gloss finish. 1st cast: Aikyd Zine Sust Netal Primer 2nd coat: Aikyd Protective Sewi-ginss Enamel. 3rd cost: Aikyd Protective Semi-gloss Enamel.

3. EXECUTION

A. General Requirements:

1. Lightly sand woodeerk to receive a clear finish prior to applying finish.

2. Resore and protect herdeare, accessories, device plates, fighting fixtures, coupletion of each space, carefully replace all removed items, Use only skiled mechanics for removal, replacement, and presented. mechanics for removal, replacement, and protection.

1. Remove dears to flaish test and bottess.

B. Sufface Proparation:

1. Bood: Sendpoper to a smeeth and even surface, then dust off. After priming coat has dried, apply shallow to surfaces to be pointed, including oil hosts, pitch, and resinous septeed after surgeing and burning. After priming cost has dried, putty all neil holes, crasts, open juints, and other defacts with lead putty. Putty shall be asieres te moten stain or seint. . . .

2, Ferrous Surfaces: Romove dirt and graase with mineral spirits. Romove rust, dill saale, and defective paint doon to sound surface, using scraper, sandyaper, or wire brush, as necessary. Touch up all spots and damaged shop soats with rest inhibitive arierf.

6. Application: Secure approval of each cost prior to proceeding with the next.

1. Apply material evening without runs, sags, or other defects. Bork each coat into the material being coated at on everyon rate of severyon ratemanded. Cover surfaces seeplatuly to provide uniform color and appearance. Lasva maidings, trim, ornaments, edges, and millbork dison and true to datails eitheut access point in corners or depressions. lake adges of paint edjoining other motorials or colors sharp and close, and without everlap

2. Pointes and Stained Bork: Jock prime exterior miliwork and finish material if untreated. Priot to or on same day of installation, prime wood siding, faces, edges, tonguos, and grooves, and exterior work. Touch up scarred and abraded places on shop or factory applies prime costs.

2. Brying Time: Binimum as recommended, Bo ast apply succeeding costs watif the . undersest is thereughly dry.

4. Sanding: Lightly sand between costs to insure that surface finish is snoeth to the touch. Exterior stained siding, soffits, fascing, and rough-seen material need not be sender

Cleanup: Remove all gaint, stain, or other finish material where it has igilled or saattored.

E. Schodule of Paint Colers: Humours shoen are pased on the Munsell Classifying Systems for point color by Bunsell Color Company, inc., Baitimore, Baryland.

1. Exterior Boors and Freess: White 2.87-8/2.

- 2. Binden Frames andissa: Baite, 2.87-8/2.
- 1. Butter and Baonsports: Not asintad.
- Cupaia: Unite, 1.87-8/2.
- Interior Trim: 2.87-8/2.
- 0. Interior Aristophilo: Balteones.

7. Root Froming and Trust: Not pointed.

PARTIAL RESTOR


SPECIFICATIONS JOHN

PGI 6.213 PREPARED DRAWING NO. BARLOW w 384 DESIGNED 25.003 w SHEET DAAWN 118 W.L.SARLOW 13 CHECKED OV. 1976


OF 11


FORT


ATI	ON	NOV. 1976		
¢	JOHN	BROWN'S		









































XI. APPENDIX C/PROJECT AGREEMENT

John Brown Fort / Flood - Storm Recovery Project / Condition Assessment Report and Preservation Repairs / February 1998



United States Department of the Interior

NATIONAL PARK SERVICE Historic Preservation Training Center 4801 A Urbana Pike Frederick, MD 21704

D18 (HPTC)

May 21, 1997

Memorandum

- To: Superintendent, Harpers Ferry National Historical Park
- From: Superintendent, Historic Preservation Training Center
- Ref.: Flood/ Storm Recovery Project; Design Assistance @ PKG 110 and John Brown Fort Repairs
- Subject: Transmittal of FINAL Project Agreement

Enclosed is the FINAL Project Agreement for the referenced project. Comments received from the Peter Dessauer and Tim Fox have been incorporated into this document. *Changes are in italics to differentiate them from the original text.*

We have included Option 1, a full scale mock-up of the approved replacement hardware as per Mr. Dessauer's suggestion. This increases the Project Total by \$1600 from \$12500 to \$14100. See Section IX. Project Cost Estimate/ Budget for further details.

Please review this final Project Agreement and upon your approval sign and return the <u>original</u> cover sheet <u>only</u> to this office; this indicates final park approval of the Project Agreement. HPTC will distribute copies of the approved cover sheet to all project team members. Based on your approval please initiate a transfer of funds (\$14100) to the Historic Preservation Training Center.

If we can provide further information or assistance regarding this project please do not hesitate to contact Tom Vitanza, Project Historical Architect at (301) 663-8206, extension 135.

Thank you for your attention to this matter.

H. Thomas McGrath, Jr.

Enclosure: Final Project Agreement

cc: (all w/c encl.) HAFE, Tim Fox, Chief of Maintenance HAFE, Bob Wilhide, Maintenance Foreman HAFE, Peter Dessauer, Park Architect NCR, Rebecca Stevens, Regional Historical Architect (FYI)



FINAL PROJECT AGREEMENT

HARPERS FERRY NATIONAL HISTORICAL PARK Harpers Ferry, West Virginia National Capitol Region, National Park Service

FLOOD / STORM RECOVERY PROJECT: DESIGN ASSISTANCE AT **PKG 110 BUILDINGS AND JOHN BROWN FORT REPAIRS** 1997

5 **Recommended:** Superintendent, Historic Preservation Training Center Date Approved: _ Date

Superintendent, Harpers Ferry National Historical Park

Prepared by: Thomas A. Vitanza Historic Architecture Team Leader **Historic Preservation Training Center** 4801 A Urbana Pike Frederick, Maryland 21704

I. PROJECT DESCRIPTION

The HPTC Historic Architecture Preservation Team has been requested to provide Harpers Ferry National Historical Park with preservation design assistance for two specific projects. Both projects are located in historic lower town which was ravaged recently by two 100 year floods in January 1996 and September 1996. As a result, the John Brown Fort, Building 63, is part of the HAFE Flood/ Storm Recovery Program and needed repairs are funded.

The first task is to provide updated preservation assistance with the exterior doors at the museum complex located in Buildings 9, 10, 11, and 12 and their respective annexes. The focus will be on the main egress doors, secondary exiting doors, and basement level doors.

The second task is to provide general preservation maintenance and flood/ storm recovery repair recommendations, drawings, and specifications for the John Brown Fort. All work to be accomplished by NPS preservation/ maintenance employees.

II. STRUCTURE DESCRIPTION

Task 1. Buildings 9, 10, 11, and 12 and their respective annexes.

Task 2. John Brown Fort, Building 63.

III. PROJECT SCOPE

Task 1. Upgrade existing hardware, doors, door frames, *and sills* at museum complex in Buildings 9, 10, 11, and 12 and their respective annexes. The project focus will be on the first floor of the complex; priorities are the main egress doors followed by the secondary exiting doors. Basement doors will be the third priority.

Update to include research into replacement of exiting hardware with more traditional yet functional hardware; panic hardware to remain, door swings will not be changed. Research and recommendations into appropriate wood species for door and door frame components. HPTC will develop a door schedule to document existing conditions and to make treatment recommendations.

Specific information will be provided for all hardware recommendations, samples will be provided where possible. Drawings will be provided for door and frame design as required.

Option 1. HPTC will arrange for a full scale mock-up of the approved replacement hardware system as a demonstration on a door chosen by the park. HPTC will arrange

89

for vendor to supply and install demonstration hardware, and replace with original or replacement hardware if not accepted by the park. NOTE, this option not included in base price for project; if park wishes HPTC to carry out this option add Option 1 amount to project total for final project amount. See Project Estimate, Section IX.

Task 2.Provide preservation recommendations for the John Brown Fort, Building63. As a result of the past two floods serious fabric deterioration has been noticed.Repairs are to be designed so that work may be accomplished using in-house NPSpreservation/ maintenance employees.

HPTC will provide an overall condition assessment report and will provide recommended treatment statements with drawings and specifications, as appropriate. HPTC will provide base line drawings for work using existing HABS drawings as base sheets, and will provide annotated photo-based report with treatment recommendations for park use.

IV. DATA COLLECTION

The development of this Project Agreement is based on numerous site meetings and telephone conversations with park management and staff in addition to background material. The following reports, correspondence, meetings, and site visits have been used to provide historical and/ or project related background information for this project, and to assist in the preparation of this Project Agreement.

Oct. 9, 1996	From: HAFE Architect, To: NCA Chief of Maintenance Subject: Design Assistance Request for PKG. 110 Doors, Bldg. 48, and John Brown Fort
Oct. 28, 1997	From: HAFE Superintendent, To: NCA Chief of Maintenance Subject: FY97 Project Reporting System - Compliance
Oct. 29, 1996	From: Superintendent HPTC, To: Superintendent HAFE Subject: HPTC Interest in Park Preservation Projects
Nov. 6, 1996	From: HAFE Superintendent, To: Chief, WPTC Subject: Storm/ Recovery Program 1997-98; Three Additional HAFE Design Projects for HPTC During 1997
Nov. 6, 1996	From: HAFE Architect, To: HPTC, NCR Mailing List Subject: Three New HAFE Design Projects for HPTC 1997

001-52-1997 13:26

- Nov. 14, 1996 On-site meeting with HAFE, HPTC and NCR Team Members Subject: Tour of flood/ storm damaged historic structures
- Dec. 16, 1996 From: HAFE Architect, To: HAFE, HPTC Mailing List Subject: Request Confirmation and Schedule
- Jan. 13, 1997 From: HAFE Architect, To: HPTC Subject: HPTC Design and Construction Work at HAFE in 1997
- Jan. 21, 1997 On-site Meeting: HAFE Superintendent, Architect. HPTC Architect Team Leader Subject: Preliminary scope of project, schedule, and estimates
- March 4, 1997 From: HPTC Architecture Team Leader, To: HAFE Architect/ Superintendent Subject: HPTC Project Update for Flood/ Storm Recovery Projects
- March 19, 1997 On-site Meeting: HAFE, DSC, and HPTC Architects, Roofing Manufacturer representative Subject: Team coordination, evaluation of existing structures
- March 26-7, 1997 Site work by HPTC Project Historical Architect & Team Leader Subject: Preliminary assessment of John Brown Fort
- April 7, 1997 From: HPTC Architecture Team Leader, To: HAFE Architect/ Superintendent Subject: Status of HPTC Projects for HAFE, No. 2
- April 7, 1997 On-site meeting: Superintendent, Assistant Superintendent HPTC, HAFE Park Architect Subject: Update HPTC Project Schedules for FY97 and FY98
- April 9, 1997 From: HAFE Architect, To: HPTC, HAFE, DSC, and NCR Project Mailing List Subject: HPTC Project Schedule Update Request
- May 6, 1997 On-site meeting; HPTC Architect Team Leader & HAFE Maintenance Foreman Subject: Inspection of PKG. 110 doorways, meet with Chief of Maintenance

V. COMPLIANCE

<u>1. National Historic Preservation Act</u>: Minimal historic building fabric will be disturbed as a result of this project, therefore no NHPA Section 106/110 compliance activities will be required for the design phase of the project. As per 10/28/96 memo, park has blanket compliance authority from the West Virginia State Historic Preservation Office to proceed with work on flood & storm damage projects throughout the park with documentation to be submitted later.

Compliance beyond that required for the National Historic Preservation Act, including all federal, state, regional and local compliance requirements and permits for this work is the responsibility of the park and shall be secured and furnished to the HPTC prior to commencement of work.

All HPTC design and treatment recommendations are in compliance with the Secretary of the Interior's Standards for the Treatment of Historic Properties and the Guidelines for Preserving, Rehabilitating, Restoring and Reconstructing Historic Buildings, and NPS-28, Cultural Resource Management Guidelines, Release No. 4.

2. Building Code and Life Safety Guidelines: HPTC treatment recommendations and project related design work complies with the following recommended guidelines as applies to the work undertaken by the scope of work identified in this Project Agreement:

- Building Officials and Code Administrator's (BOCA) National Building Code, 1996.
- National Fire Protection Association (NFPA) Life Safety Code and Handbook, 1997
- Uniform Federal Accessibility Standards, 1991
- Americans with Disabilities Act Accessibility Guidelines

3. Project Related:

Task 1. No changes will be made to the exiting (panic) hardware and egress capacity of the museum complex. This project will have no impact on building code or life safety related issues. The NFPA Life Safety Code and Handbook will be used as the basis for evaluation of all door hardware criterion. Recommendations for reconstruction of existing doors and door frames will not impact other code related exiting requirements.

Task 2. The scope of this project, flood/ storm recovery repairs and preservation maintenance, will not impact any life safety or building code related issues.

VI. **PROJECT COORDINATION**

-~

The success of any project depends on the timely coordination and completion of all necessary actions as outlined for each of the following parties to this Project Agreement, Task 1 and Task 2.

HPTC

Prepare Project Agreement including cost estimate and schedule.

Schedule and conduct project related meetings and review sessions as required to successfully complete project.

Coordinate field work, fabric investigation, documentation, etc., and phasing of the development of project documents, and meet as necessary with HAFE Park Architect and HAFE Maintenance.

Review all existing documentation including investigative and historical reports, correspondence, etc. for project development.

Designate a project architect/ supervisor to be primary point of contact with HAFE on project related issues.

Provide project supervision, team, materials, supplies, equipment, travel and transportation for all work performed by HPTC.

Provide project staff for duration of project to complete scope of work according to project schedule. Notify park management if slippage in project schedule becomes apparent, revise project schedule accordingly with park input.

Provide project products as specified in Section VII.

HAFE

Provide transfer of project funds to HPTC upon approval of Project Agreement.

Provide treatment and use decisions in a timely manner, and respond to all inquiries by HPTC staff for determination of design issues.

Designate a single project manager/ administrative contact to coordinate the park response to issues of treatment and use, review comments, etc. and with responsibility to communicate with HPTC and to act as liaison.

Provide copies of/ access to all known park files, reports, archives, library materials which may have a bearing on the outcome of this project.

Provide technical and review input and comments in a timely manner.

Provide keyed access to park structures as affected by this project.

Provide any necessary compliance documents prior to the start of work.

NCR

Provide professional support from Regional and system support office cultural resources staff for technical, compliance, and code related issues.

VII. PRODUCTS

Products to be furnished by the HPTC to HAFE as a result of the approval of this Project Agreement are listed below. All design and treatment recommendations will be prepared for implementation by NPS based preservation/ maintenance employees.

Task 1. Door Schedule and written report will address treatment recommendations for the improvement of the operation and maintenance of subject doors. Report will include brief condition assessment, inventory, and treatment recommendations for improving operability and maintenance. Drawings and specifications (including technical information regarding manufacturers, products, warrenties, etc.) will be provided.

Task 2. Base line drawings to document treatment recommendations; HPTC will use existing HABS and HAFE drawings as base sheets for presentation of treatment recommendations. Annotated photo-based report with condition assessment, inventory, and treatment recommendations will supplement the drawings and include specifications and details as required for implementation of the work.

Four copies of each document will be provided to the park. Any original photographs and negatives will be transmitted to the park at the completion of the project. Any original mylar drawing sheets will be transmitted to the National Capital Region, Stewardship and Partnerships, Division of Land Use Coordination Records Office, Room 208, 1100 Ohio Drive, SW, Washington, D.C. 20242, (202) 619-7124.

NOTE: Any Changes, Modifications, or Amendments to the approved Project Agreement will be documented through the use of the HPTC Design Change Approval Form, Appendix 1. -

VIII. 1997 PROJECT SCHEDULE

- As per agreement of April 7, 1997
- Project Agreement by end of May 1997
- Transfer of funds upon park approval of Project Agreement
- Task 1: Project priority items completed by mid June 1997, secondary items to follow in July 1997
- Task 2: Project products completed by end of July 1997

IX. PROJECT COST ESTIMATE / BUDGET

♦♦♦	Task 1:	Including work to date, additional field work, hardware research, preparation of schedule and recommendations	\$	4000
♦ ♦	Task 2:	Including work to date, additional field work, preparation of treatment recommendations presentation		****
♦		I Transportation phics and Copying	\$ \$	300 1500
♦ ♦	<u>Sub Total</u> HPTC Ove Project T e		\$	<u>9400</u> 3100 1 2500
\$	Option 1 (Overhead included)	\$	1600
	PROJECT	TOTAL WITH OPTION 1 ADDED	\$	14100

NOTE: HPTC salaries are calculated on a pay period basis. The hourly rate for each occupation is determined by combining the direct hourly pay rate plus benefits with a prorated amount for the indirect costs of annual and sick leave, holidays, and training. The number of pay periods is based upon an estimate of the total number of hours required for each team member to complete the required project tasks. As this is based on previous project experience with an approved scope of work this should be considered a Class B estimate.

X. PROJECT PARTICIPANTS

HAFE Peter Dessauer, Park Architect, Project Manager Tim Fox, Chief of Maintenance Gayleen Boyd, Funding Point of Contact

HPTC Torn Vitanza AIA, Project Historical Architect, Project Manager Doug Hicks, Assistant Superintendent Norma Dale, Funding Point of Contact

XI. TRAINING OBJECTIVES

No formal training objectives have been developed as it is anticipated this project will be completed by HPTC senior staff. If interns or coop students become available during the course of this project training objectives will be developed. All work will be under direct supervision of Maryland Registered Architect.

XII. APPENDICES

A. HPTC Design Change Approval Form

End of Document

TAVitanza:tav:05/12/97:a:WP5.1/2:fsrp97pa.dpa TAVitanza:tav:05/21/97:a:WP5.1/2:frsp97pa.fpa

OT