

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

**NATIONAL REGISTER OF HISTORIC PLACES
INVENTORY -- NOMINATION FORM**

FOR FEDERAL PROPERTIES

FOR NPS USE ONLY	
RECEIVED	
DATE ENTERED	

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS
TYPE ALL ENTRIES -- COMPLETE APPLICABLE SECTIONS

1 NAME

HISTORIC
Rangers' Club
AND/OR COMMON
Rangers' Club

2 LOCATION

STREET & NUMBER
Yosemite Valley
CITY, TOWN
Yosemite National Park
STATE
California
VICINITY OF
15th
COUNTY
Mariposa
CODE
06
CONGRESSIONAL DISTRICT
15th
CODE
043

3 CLASSIFICATION

CATEGORY	OWNERSHIP	STATUS	PRESENT USE
<input type="checkbox"/> DISTRICT	<input checked="" type="checkbox"/> PUBLIC	<input checked="" type="checkbox"/> OCCUPIED	<input type="checkbox"/> AGRICULTURE <input type="checkbox"/> MUSEUM
<input checked="" type="checkbox"/> BUILDING(S)	<input type="checkbox"/> PRIVATE	<input type="checkbox"/> UNOCCUPIED	<input type="checkbox"/> COMMERCIAL <input type="checkbox"/> PARK
<input type="checkbox"/> STRUCTURE	<input type="checkbox"/> BOTH	<input type="checkbox"/> WORK IN PROGRESS	<input type="checkbox"/> EDUCATIONAL <input type="checkbox"/> PRIVATE RESIDENCE
<input type="checkbox"/> SITE	PUBLIC ACQUISITION	ACCESSIBLE	<input type="checkbox"/> ENTERTAINMENT <input type="checkbox"/> RELIGIOUS
<input type="checkbox"/> OBJECT	<input type="checkbox"/> IN PROCESS	<input checked="" type="checkbox"/> YES: RESTRICTED	<input type="checkbox"/> GOVERNMENT <input type="checkbox"/> SCIENTIFIC
	<input type="checkbox"/> BEING CONSIDERED	<input type="checkbox"/> YES: UNRESTRICTED	<input type="checkbox"/> INDUSTRIAL <input type="checkbox"/> TRANSPORTATION
		<input type="checkbox"/> NO	<input type="checkbox"/> MILITARY <input checked="" type="checkbox"/> OTHER: Gov't Residence

4 AGENCY

REGIONAL HEADQUARTERS: (If applicable)
National Park Service - Western Regional Office

STREET & NUMBER
450 Golden Gate Avenue - Box 36063
CITY, TOWN
San Francisco,
STATE
California
VICINITY OF

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,
REGISTRY OF DEEDS, ETC. National Park Service - Western Regional Office

STREET & NUMBER
450 Golden Gate Avenue - Box 36063
CITY, TOWN
San Francisco
STATE
California
VICINITY OF

6 REPRESENTATION IN EXISTING SURVEYS

TITLE
1) Yosemite Valley-EVALUATION OF HISTORIC RESOURCES, By E. N. Thompson
2) List of Classified Structures Inventory
3) National Register of Historic Places

DATE
1) 1974
2) 1975 3) 1977
 FEDERAL STATE COUNTY LOCAL

DEPOSITORY FOR SURVEY RECORDS
1) National Park Service - Denver Service Center
2) & 3) National Park Service
CITY, TOWN
1) Denver
2) & 3) Washington
STATE
Colorado
D. C.

7 DESCRIPTION

CONDITION		CHECK ONE	CHECK ONE
<input type="checkbox"/> EXCELLENT	<input type="checkbox"/> DETERIORATED	<input type="checkbox"/> UNALTERED	<input type="checkbox"/> ORIGINAL SITE
<input type="checkbox"/> GOOD	<input type="checkbox"/> RUINS	<input checked="" type="checkbox"/> ALTERED	<input type="checkbox"/> MOVED DATE _____
<input checked="" type="checkbox"/> FAIR	<input type="checkbox"/> UNEXPOSED		

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Rangers' Club is a two-and-a-half story wood frame structure with a granite rubble foundation. The building is U-shaped in plan with a small courtyard on the inside of the "U". Exterior walls are finished with redwood shingles with the exception of the gable ends which are board-and-batten vertical siding. The building is stained brown with a gold-ochre trim painted around window frames. All of the corners of the building are edged with peeled log pilasters that run from the foundation to the eaves. A wood terrace centered on the south elevation is flanked by bay windows at its east and west edges. The corners of the bays and the terrace are also edged with peeled logs, like the other building corners. The log pilasters on the corners originally extended through the roof. The extending portions were cut back to the roofline by 1932. All of the gable ends of the building have second-story balconies. The balconies have jigsaw railings, reminiscent of chalet buildings. Decorative jigsaw work is repeated in the lower portions of the board-and-batten siding at the gable ends, in the attic vents, and in the fine interior woodwork. Fire escapes of wood planks and log railings were added at the north end balconies of the wings in 1947. Wood ladders on the east and west gables were probably added at the same time.

The roofs are steeply pitched and contribute a substantial amount to the building's character. The roofs are finished with wood shingles and are pierced by multiple dormers that increase the interior space and provide additional light to the second-story rooms. Dormers in the south (main) wing have shed roofs. Those on the east and west wings have gable roofs on the outside portions of the "U" and shed roofs on the inside portions of the "U."

A massive granite chimney is centered on the north wall of the courtyard.

The rooms retain their original configurations. The most important interior spaces are the common rooms on the first floor--the dining room, living room, and the north and south nooks off the small connecting hallway between them. The nooks are defined by bookshelves that rise halfway to the ceiling and that partition off that intermediate space between the living room and dining room. The backboards of the bookcases have fir tree designs sawn into the wood. Wood posts and pilasters along the walls of the dining room and living room and edging the bookcases are chamfered, with sawn corbel capitals. The posts support composite beams that have chevron-patterned trim on their lower edges. Hewn ceiling joists above the beams support the rough wood ceiling, laid in a diagonal pattern. The carved

**United States Department of the Interior
National Park Service****National Register of Historic Places
Inventory—Nomination Form**

For NPS use only

received

date entered

Continuation sheet

Item number 7

Page 2

portion of the chevron and the ceiling boards have a light-colored stain finish, which contrasts with the dark beams, joists, and wall paneling, and emphasizes the zig-zag of the chevron and the strong lines of the ceiling joists. The ornamental designs of forest, alpine, and Indian cultural elements add a quality of rusticity to the space. All of these spaces have a wall treatment of a dark, wood-paneled wainscoting with a plaster finish above. This treatment is repeated throughout the hallways of the building. The walls of the staircases to the second floor have a dark wood paneling. Twelve-light french doors provide access from the living room to the wood terrace at the south side of the building.

Original furnishings remain in the dining room and main living room. These include trestle tables and benches of four-inch thick sequoia planks. A wagon-wheel chandelier hangs in the living room, centered in front of the fireplace. Small lamps with leather shades are on the posts and walls of the common spaces. The nooks each have ceiling lamps hanging above the tables; the lamps sport a fringe made of giant sequoia cones. Most of the rooms have kept the original wood-dowel curtain rods. A bronze plaque commemorating Stephen T. Mather, first director of the National Park Service, is to the left of the fireplace. A painting of Mather is directly over the granite fireplace.

The second story has a U-shaped hallway with single and dormitory rooms, and shared baths along its outside edges. Some of the single rooms have their own baths. The partial basement houses laundry facilities and mechanical equipment. The walls of the staircase down into the basement are finished with beaded siding. Floors throughout the building are wood, with the exception of the concrete floor in the partial basement. The wood floors are covered with large rugs in the common rooms and are covered with linoleum in the kitchen and bathrooms.

The kitchen area and bathrooms throughout the building have been updated with new materials. A ramped entrance was added to the northeast (kitchen) wing to accommodate employees in wheelchairs. Considerable preservation work was done on the south elevation of the structure including jacking up the building, rebuilding part of the foundation, and replacing wood, to counteract rot and subsidence. All of this work was completed approximately ten years ago. A fire detection and suppression system was added to the building. The men's dormitory section has new partitions that were added in 1979 so that occupants could have more privacy. The original heating system was electric but was abandoned in 1933 when steam heat was installed. The building's

**United States Department of the Interior
National Park Service**

**National Register of Historic Places
Inventory—Nomination Form**

For NPS use only

received

date entered

Continuation sheet

Item number 7

Page 3

present electric baseboard heat was installed prior to 1973.

To the east of the Rangers' Club is the garage-woodshed that was constructed to match the Club. The building is L-shaped in plan, with steeply pitched gable roofs, shingle siding, and board-and-batten gable ends. To the west is a small wood-frame transformer house, also constructed with similar features. Only the exterior of these additional structures are included as part of this landmark nomination.

The only intrusions within the boundaries are a series of portable metal storage lockers on skids near the garage, and the fire hydrants on the property. The vegetation has flourished around the building in recent years, making it difficult to photograph.

9 MAJOR BIBLIOGRAPHICAL REFERENCES

SEE ATTACHED.

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY Approx. 4.5 acres

UTM REFERENCES

A 1 1 | 2 7 2 0 8 5 | 4 1 8 0 7 2 5
 ZONE EASTING NORTHING

B | |
 ZONE EASTING NORTHING

VERBAL BOUNDARY DESCRIPTION

The landmark boundary is shown as the dotted line on the attached park planning map beginning at a point on the south side of the access road (bus route) 50' east of eastern edge of the existing Rangers' Club parking lot proceeding in a south-southeasterly direction to the northern edge at the highway, then proceeding in a westerly direction to the northern edge at the highway, then proceeding in a westerly direction along the edge of the highway 500', then proceeding north to a point on the access road (bus route)

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

directly south of the Center intersection of the administration road and the access road then East to starting point.

STATE	CODE	COUNTY	CODE

11 FORM PREPARED BY

NAME / TITLE

Laura Soulliere Harrison, Architectural Historian

ORGANIZATION

National Park Service

DATE

1985

STREET & NUMBER

P.O. Box 728

TELEPHONE

505-988-6787

CITY OR TOWN

Santa Fe

STATE

New Mexico

12 CERTIFICATION OF NOMINATION

STATE HISTORIC PRESERVATION OFFICER RECOMMENDATION

YES ___ NO ___ NONE ___

STATE HISTORIC PRESERVATION OFFICER SIGNATURE

In compliance with Executive Order 11593, I hereby nominate this property to the National Register, certifying that the State Historic Preservation Officer has been allowed 90 days in which to present the nomination to the State Review Board and to evaluate its significance. The evaluated level of significance is ___ National ___ State ___ Local.

FEDERAL REPRESENTATIVE SIGNATURE

TITLE

DATE

FOR NPS USE ONLY

I HEREBY CERTIFY THAT THIS PROPERTY IS INCLUDED IN THE NATIONAL REGISTER

DATE

DIRECTOR, OFFICE OF ARCHEOLOGY AND HISTORIC PRESERVATION

ATTEST:

DATE

KEEPER OF THE NATIONAL REGISTER

**United States Department of the Interior
National Park Service**

**National Register of Historic Places
Inventory—Nomination Form**

For NPS use only

received

date entered

Continuation sheet

Item number 8

Page 2

Mather's love affair with Yosemite began before his employment with the Department of the Interior. As director of the new agency one of his early decisions was to move the development of Yosemite Valley from the south side to the north. Included in the new development he proposed were a museum, post office, and headquarters building. In conjunction with that development Mather saw the need for a special structure to house members of his newly organized ranger force. The withdrawal of Army troops (with the exception of Army Engineers) from park areas and the burgeoning tourist industry created the perfect situation for Mather to proceed with his ideas for employing park rangers who could guide tourists and answer their questions as well as arrest poachers and vandals. As a donation to the National Park Service, Mather hired the architect and had the structure built at his own expense to house members of that force.

Horace Albright felt that Mather had additional reasons for constructing and donating the building. Albright wrote in 1976: "Mr. Mather also decided to build a rangers' clubhouse in the new village, hoping Congress would be pleased with it and give him money for ranger clubhouses in other parks -- something that never happened. Mr. Mather employed a highly regarded architect of San Francisco to design the Yosemite clubhouse. He was Charles Sumner Kaiser, but because the name "Kaiser" was a name condemned everywhere in World War I, this architect had a court action drop "Kaiser" from his name; so the architect of the Clubhouse was Sumner." [2]

Sumner designed a fine structure--a large, rustic, modified chalet with wood shingles and board-and-batten siding, and steeply pitched roofs. Instead of leaving simple corners, every edge of the building was defined with heavy log pilasters, strengthening the connection between the building and surrounding forest edges. The steep roofs shed the winter snows and emphasized the structure's verticality. The natural materials further harmonized the building with its setting while the decorative railings on the balconies and terrace evoked images of European chalet precedents. On the interior the common spaces were treated with an Arts-and-Crafts warmth--stout wood furnishings, dark wood paneling, built-in bookcases with the added touch of jigsawn fir trees in the woodwork, wagon-wheel and cone-fringed chandeliers, exposed beams with chevron designs. The building suggested a sense of wilderness in form and design, tempered with allusions to frontier and alpine traditions.

Mather did succeed in moving the development center of the Yosemite Valley to the north side of the valley, and the Ranger's

**United States Department of the Interior
National Park Service**

**National Register of Historic Places
Inventory—Nomination Form**

For NPS use only

received

date entered

Continuation sheet

Item number 8

Page 3

Club was the first of the major structures built there. For the most part the building's type of rustic chalet design was not followed in future park architecture, but it did succeed as an inspiration for a wide range of variations in rustic design. The building's strong rustic character and intimate connection with the first director of the National Park Service make it unique in the National Parks.

1. William C. Tweed, Laura E. Soulliere, and Henry G. Law, National Park Service Rustic Architecture: 1916-1942 (San Francisco: National Park Service, 1977), p. 23.
2. Letter of Horace M. Albright to William C. Tweed, June 4, 1976.

**United States Department of the Interior
National Park Service**

**National Register of Historic Places
Inventory—Nomination Form**

For NPS use only

received

date entered

Continuation sheet

Item number 9


Page 1

Ise, John. Our National Park Policy: A Critical History.
Baltimore: Johns Hopkins Press, for Resources for the Future,
1961.

LaFleur, Harold. Historic Structure Report: Rangers' Club,
Yosemite National Park, California. Denver: National Park
Service, Denver Service Center, September, 1973.

Letter of Horace M. Albright to William C. Tweed, June 4, 1976.

Tweed, William C., Soulliere, Laura E., and Law, Henry G.
National Park Service Rustic Architecture: 1916-1942. San
Francisco: National Park Service, 1977.



UPPER

TECOYA

Utility Building

Warehouse & Maintenance

VISITOR CENTER

Admin

Ranger Club

School

PC

Cogan's

RESIDENTIAL AREA

LANDMARK BOUNDARY



Rangers' Club, south elevation

Yosemite National Park

NPS photo by Laura Soulliere Harrison

9/85



Rangers' Club, from the northwest

Yosemite National Park

NPS photo by Laura Soulliere Harrison
9/85



Rangers' Club dining room

Yosemite National Park

NPS photo by Laura Soulliere Harrison

9/85



Rangers' Club Garage, north elevation

Yosemite National Park

NPS photo by Laura Soulliere Harrison
9/85



Rangers' Club, from the northeast

Yosemite National Park

NPS photo by Laura Soulliere Harrison

9/85




Detail of woodwork, living room

Rangers' Club

Yosemite National Park

NPS photo by Laura Soulliere Harrison

9/85



Original furnishings, living room

Rangers' Club

Yosemite National Park

NPS photo by Laura Soulliere Harrison

9/85



Fireplace with portrait of Stephen Mather
hanging above

Rangers' Club

Yosemite National Park

NPS photo by Laura Soulliere Harrison

9/85



Original light fixtures, chevron-patterned
beam, and nature-oriented jigsaw work

Rangers' Club

Yosemite National Park

NPS photo by Laura Soulliere Harrison

9/85




Nook between living room and dining room.
Note woodwork and built-in bookshelves.

Rangers' Club

Yosemite National Park

NPS photo by Laura Soulliere Harrison
9/85



Original furnishings in nook between
living room and dining room

Rangers' Club

Yosemite National Park

NPS photo by Laura Soulliere Harrison

9/85



Rangers' Club, from the northeast

Yosemite National Park

NPS photo by Laura Soulliere Harrison
9/85



Looking from living room into dining room

Rangers' Club

Yosemite National Park

NPS photo by Laura Soulliere Harrison

9/85