



*Cut no deeper into heavy bark trees than necessary to make clear blaze. Don't cut into sap. A clear blaze can be made otherwise. See to it that axe-men do not exceed dimension given.*