

Chart No. 3

Location of Interior Repair and Improvement  
Work at Arlington House and Amount Expended  
1895-1904

(Approximate)

Years	Public Rooms Center-South Wing	North Wing (Supt. Qrs.)	2nd Floor (Rhodes' Qrs.)	Basement	Total
1895					
1896					
1897	--	--	--	\$ 13.00	\$ 13.00
1898	111.00	18.00	83.00	4.00	216.00
1899	72.00	226.00	100.00		398.00
1900		38.30		15.00	53.30
1901	29.00		4.00	8.00	41.00
1902	251.00	10.00		96.00	357.00
1903	6.00	2.50	138.00	6.50	153.00
1904				5.00	5.00
Total	\$469.00	\$294.80	\$325.00	\$147.50	\$1,236.30