Lock

No.

4


("Red

Lock"

OHIO HISTORIC	INVENTORY JUN	2 (137) Ohio Historical Center Columbus, Ohio 43211	
. No. 8 . County Summit	4. Present Name(s) Lock No. 34 ("Red Lock") 5. Other Name(s)		8 9 5
I. Location of Negatives OHS			
Specific Location orth side of Highland Rd. ust east of the Cuyahoga iver	16. Thematic Category	28. No. of Stories	S.
		29. Basement? Yes 🗆	umm m
	17. Date(s) or Period 1825–1827	No 🗆	135
		30. Foundation Material	ii.
City or Town if Rural, Township & Vagamore Hills			1
		31. Wali Construction	L
VAUGNU RA.	19. Architect or Engineer	load-bearing masonr	I
	v .	32. Roof Type & Material	l
		OO No of Bone	!
	21. Original Use, if apparent	33. No. of Bays Front Side	r.
	A MIZI. URUMAN USB. N ADDAMAN		- 0 '

canal lock

22. Present Use



Lat. Long U.T.M. Reference

1 7 452720 4|5|7|0|8|0|0 Zone Easting Northing 10. Site Structure 2 Building Object

11. On National Yes 🖄 Yes 🗆 Eligible? Register? No 🍱 No □ 13. Part of Estab. Yes 🗆 14. District Yes 🖾 Hist. Dist.? No 🍱 Potent'i? No 🗆

15. Name of Established District

23. Ownership Public 🗷 Private 🗆 24. Owner's Name & Address,

Statte owof O. Dept. of Public 37. Condition Works

65 S. Front St., Columbus 25. Open to Yes 🏻 Public? unrestricted

26. Local Contact Person or Organization Summit County Hist. Soc. 27. Other Surveys in Which Included historic civil engineering

landmark, Ohio Council ASCE

Approx. Acreage: less than 1

34. Wall Treatment cut stone/concrete 35. Plan Shape rectangle

36. Changes Addition 🗇 Altered 🏖 (Explain Moved in #42)

fair XXXXX XXXXENO 38. Preservation Yes Underway? No 🕃

39. Endangered? Yes 🗆 By What? No 🕱 40. Visible from **Public Road?**

Yes 🗆 No DE 41. Distance from and Frontage on Road

42. Further Description of Important Features Lock is standard mitered gate type. The lock chamber is 90 feet long by 15 feet wide. The cut stone construction was repaired with concrete c. 1905. Both gates are missing. There is water in the lock chamber, though the canal is

dry at this point. The lock is almost obscured by thickets. Stonework and concrete are deteriorated.

43. History and Significance hat portion of the Ohio & Erie Canal between Akron and Cleveland was opened uly 4, 1827. The drop of 395 feet between the two cities was accomplished y 41 locks in 35 miles. At least one local history gives the name "Red Lock" or Lock No. 34, but it does not suggest the origin of that name. Wilcox ritten that all woodwork of the locks and sluices was painted Indian red.

44. Description of Environment and Outbuildings

Located off rural road in the vicinity of the Jaite Paper Mill. and surrounding land has become a dumping ground.

45. Sources of information

The Brecksville Historical Association, A Reminiscent History of Brecksville (Berea, O.: Berea Publishing Company, 1961), p. 22.

Frank Wilcox, The Ohio Canals, selec. and ed. William A. McGill (Kent, O.: Kent State University Press, 1969).

46. Prepared by Carol Poh Miller

47. Organization

48. Date 49. Revision Date(s) 4/76



Thematic Resources

Lock No. 34 ("Red Lock"), Ohio and Erie Canal District, Cuyahoga and Summit Counties, Ohio Photograph by Carol Poh Miller, April Negative property of Ohio Historic Preservation Office, Ohio Historical Society View looking north. JUN 2 7 1979 #8919 DEC 1 1 1979