PN 6/82 1. SITE I.D. NO	INVENTOR	Pacific Northwest Re	gion 2001 Sixth	Westin Building, P 1920 2001 Sixth Avenu Seattle, Washington 98121		
2 NAME(S) OF STRUCTURE (CARD 1 of 2)	5. ORIGINAL USE 7.	CLASSIFICATION		9. RATING		
Ipsut Creek Ranger Cabin	Patrol Cabin			10. DATE		
3. SITE ADDRESS (STREET & NO)	Ranger Cabin and Employee	TUTM ZONE LEASTING	NORTHING	1933		
Ipsut Creek Campground C-250	Residence					
4 CITY/VICINITY COUNTY Carbon River Entrance Pierce	state s Washington	CALE 1:24 1:62.5 OTHER	QUAD NAME			
12 OWNER/ADMIN ADDRESS NPS/Mount Rainier National Park, Tahoma 13 DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S). IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC.						
Log frame one room one story rectangul	ar cabin: medium pitched	cedar shake gable ro	of extends over	an enclosed		


Log frame, one room, one story, rectangular cabin; medium pitched cedar shake gable roof extends over an enclosed rear shed lean-to; brick chimney and skylight on rear roof slope; log rafters and purlins; whole log walls; saddle notch cornering; stone rubble foundation; exposed ceiling with 2 x 6 tongue and groove sheathing; varnished interior walls; plywood flooring.


Built in 1933 by the National Park Service and similar in design to patrol cabins at Huckleberry Creek, Lake James, and Three Lakes, this cabin was constructed from plans drawn up by the NPS Branch of Plans and Design (MDRA DRG. NO.3000-A). The Drysdale Report on Construction (1933) stated: "Built on 18" cedar log footings and the side wall logs were of fir, varying from 14" at the base to 11" at the top of the walls. All of the wall logs were grooved for chinking and were chinked with rope oakum. The roof consisted of cedar shakes laid 14" to weather on 1" solid sheathing, and 8" pole rafters spaced 2'4". The floor was built of solid 2 x 4's on 8" log stringers spaced two feet, which were seven 2'4" x 4'0" windows, two on each end, two in the rear, and one in the front; and one 2'8" x 6'6" slab doors."

The cabin measures 14'2" x 23'10", with a floor size of 336 square feet. The rear lean-to wood shed is 6'0" x 16'3",

16. SIGNIFICANCE

Constructed during the administration of Superintendent O.A. Tomlinson for use as a backcountry patrol facility, this cabin was a component of the early park policy to develop a string of shelters and cabins around the park to accommodate backcountry rangers on patrol, and provide shelter for the hiking public. One of the several patrol cabins at Mount Rainier was constructed from plans drawn up by the NPS Branch of Plans and Design in San Francisco, under the supervision of Acting Chief Architect W.G. Carnes.





19. PUBLIC ACCESSIBILITY YES, LIMITED YES, UNLIMITED 20 EXISTING INB INHI THARS THATED IN	18. LOCATED IN AN HISTORI	C DISTRICT?	s Ano	NAME	
NO UNKNOWN SURVEYS COUNTY LOCAL OTHER	19. PUBLIC ACCESSIBILITY	YES, LIMITED NO		ITED	20. EXISTING NR NHL HABS HAER-1 HAER MPS STATE SURVEYS COUNTY LOCAL OTHER

Building File C-250, Maintenance Division, Mount Rainier National Park; prepared by Drysdale Report on Construction, 1933; building data, sketch plan, and photo, 1962; photo, 1977.

Original Drawing, "Standard Patrol Cabin," NPS Branch of Plans and Design, rec. by W.G. Carnes, Acting Chief Architect, 11/2/33, (MDRA DRG. NO.3000).

22. INVENTORIED BY

David Harvey


AFFILIATION

MORA Cultural Resources Survey

9/30/82

Pt 6/82		National Park Service Pacific Northwest Region	Westin Building, F 2001 Sixth Avent	
1. SITE I.D. NO	INVENTO	RY Cultural Resources Division		
2 NAME(S) OF STRUCTURE	5. ORIGINAL USE	7. CLASSIFICATION	9. RATING	
(CARD 2 of 2)				
Ipsut Creek Ranger Cabin	Patrol Cabin		10. DATE	
3 SITE ADDRESS (STREET & NO)	Ranger Cabin		1933	
Ipsut Creek Campground C-250	and Employee Residence	8. UTM ZONE EASTING NO	ORTHING 11. REGION	
Carbon River Entrance Pierce V	state Washington	SCALE 1:24 1:62.5 OTHER	QUAD NAME	
OWNER/ADMIN ADDRESS NPS/Mount Rainier National Park, Tahoma Woo				
DESCRIPTION AND BACKGROUND HISTORY INCLUDING CONSTRUCTION DATE(S). PHYS IMPORTANT BUILDERS, ARCHITECTS, ENGINEERS, ETC. with an earth floor. It has a wood frame were the cabin is in excellent condition, with coneed to be replaced. The cabin, originally a patrol cabin, now a adjacent Ipsut Creek Campground.	with 1×5 tongue and only minor rot on the	groove siding and log post exposed corner ends. Some	of the roof shakes	
14 CONDITION EXCELLENT GOOD FAIR	DETERIORATED	RUINS 15. DANGER OF DEMOLITION? (SPECIFY THREAT)	JAES NO NUKNOMN	

16. SIGNIFICANCE



AFFILIATION

DATE

22. INVENTORIED BY

United States Department of the Interior National Park Service

National Register of Historic Places Continuation Sheet

Sec	ctic	on number Page			
M	ſt.	Pani	Cor	unties, WASHINGTON	
		Substantive Review		Signature and Date Li	sted
C	cov	ER		3/1	3/91
1		Ohanapecosh Comfort Station No. 0-302	X	autowell que	3/13/91
2	2.	Ohanapecosh Comfort Station No. 0-303	<u>\</u>	automett 7 bee	3/13/91
3	3.	Three Lakes Patrol Cabin	×	automoth Thee	3/13/91
4		Camp Muir		3/13/	91
· ~ 5		Cinook Pass Entrance Arch	X	autowood flee	3/13/9/
6		Christine Falls Bridge	X	automost que	3/13/91
7		Edith Creek Chlorination House	X	autourde The	3/13/91
8		Gobbler's Knob Fire Lookout	X	automette Thee	3/13/9/
9		Huckleberry Creek Patrol Cabin	X	antoende ghos	3/13/91
. 1	0.	Indian Bar Trail Shelter	X	automielt que	3/13/91
1	1.	Indian Henry's Patrol Cabin	×	auroment thee	3/13/91
1.	2.	Ipsut Creek Patrol Cabin	X	automos 1 lee	3/13/91
. 1	3.	Lake George Patrol Cabin	X	autometa sha	3/13/91
. 1	4.	Longmire Campground Comfort Station No. L-302			3/13/91
1.	5.	Longmire Campground Comfort Station No. L-30	3		3/13/91
1	6.	Longmire Campground Comfort Station No. L-304			3/13/91
1	7.	Longmire Historic District		3	2/3/91
18	8.	Mowich Lake Patrol Cabin	×	autoenth gless	3/13/9/
19	9.	Mt. Fremont Fire Lookout	X	autoinetti glee	3/13/91
20	0.	Narada Falls Bridge	X	aurometh Thee	3/13/91
21	1	Narada Falls Comfort Station	Y	Autoriente Mese	2/12/6


UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES EVALUATION/RETURN SHEET

REQUESTED ACTION: NOMINATION
PROPERTY Ipsut Creek Patrol Cabin NAME:
MULTIPLE Mt. Rainier National Park MPS NAME:
STATE & COUNTY: WASHINGTON, Pierce
DATE RECEIVED: 1/29/91 DATE OF PENDING LIST: 2/12/9 DATE OF 16TH DAY: 2/28/91 DATE OF 45TH DAY: 3/15/9 DATE OF WEEKLY LIST:
REFERENCE NUMBER: 91000181
NOMINATOR: FEDERAL W P5
REASONS FOR REVIEW:
APPEAL: N DATA PROBLEM: N LANDSCAPE: N LESS THAN 50 YEARS: OTHER: N PDIL: N PERIOD: N PROGRAM UNAPPROVED: REQUEST: N SAMPLE: Y SLR DRAFT: N NATIONAL:
COMMENT WAIVER: N
$\sqrt{\text{ACCEPT}}$ RETURN REJECT $\frac{3/3/4/}{\text{DATE}}$
ABSTRACT/SUMMARY COMMENTS:
Ipont Creek Patrol Calin is riginficant as representative of
Sport Creek Patrol Calin is rignificant as representative of the thematic group of spatrol calins and trail shetters in
Mount Raivier notronal Park.

RECOM./CRI	TERIA Clescy / A+C
REVIEWER	autoweth live
DISCIPLINE	thistory
DATE3/	3191

CLASSIFICATION	
countresource type	
STATE/FEDERAL AGENCY CERTIFICATION	ON
FUNCTION	ATSALIOTIA CLAVE
historiccurrent	COLTANINO
DESCRIPTION	A section of the property of t
<pre>architectural classificationmaterialsdescriptive text</pre>	
SIGNIFICANCE	
Period Areas of Significan	ceCheck and justify below
Specific dates Bu Statement of Significance (in on-	ilder/Architect e paragraph)
summary paragraphcompletenessclarityapplicable criteriajustification of areas checkedrelating significance to the contextrelationship of integrity tojustification of exceptionother	resource
W. Santana and A.	
BIBLIOGRAPHY	
GEOGRAPHICAL DATA	
acreageverbal bounda UTMsboundary just	
ACCOMPANYING DOCUMENTATION/PRESE	NTATION
sketch mapsUSGS maps _	photographspresentation
OTHER COMMENTS	
Questions concerning this nomina	<u> </u>
	Phone
Signed	Date



Ipsut Creek Ranger Station (c-250)

#71
Photo 71

Please refer to the map in the Multiple Property Cover Sheet for this property

Multiple Property Cover Sheet Reference Number: <u>64500707</u>