

CLASSIFIED STRUCTURE FIELD INVENTORY REPORT
(Attach 4" x 5" Black and White Photograph)

REGION RMR PARK/AREA NAME Zion National Park PARK NUMBER 1590

STRUCTURE NAME East Entrance Sign STRUCTURE NUMBER 73

LOCATION OF STRUCTURE East Entrance PARK LOCATION CODE EE

NATIONAL REGISTER _____ DATE: / / MANAGEMENT CATEGORY: (A) (B) (C) (D)

NPS LEGAL INTEREST FEE MANAGEMENT AGREEMENT: _____

Check all of the following categories for which NPS has treatment responsibility:

Stabilization() Cyclic Maintenance() Routine Maintenance() Approved Ultimate Treatment()

(ROCKY MOUNTAIN REGION USE ONLY)

APPROVED ULTIMATE TREATMENT OR RESOURCE MANAGEMENT PLAN, CULTURAL COMPONENT DESIGNATION:

Preservation (PP)	Restoration (RR)	Reconstruction (CC)
Adaptive Preservation (AP)	Adaptive Restoration (AR)	Adaptive Reconstruction (AC)
Neglect (NG)	Remove (RM)	No Approved Treatment (NO)

Approval Document _____ () Document Date: / /

Estimated Treatment Costs _____

Stabilization: \$ _____	Date: <u> / /</u>	Level of Estimate: (A) (B) (C)
Approved Treatment: \$ _____	Date: <u> / /</u>	Estimator: (Region) (DSC) (A&E)

STATEMENT OF SIGNIFICANCE:

Date of Construction: / / 1935 Date of Alterations: / /
Architect/Designer: _____ Historical Theme(s): NPS Structures - Rustic
History of Structure: The East Entrance sign was built by enrollees of Camp NP-2, stationed at Zion, in 1935. A year earlier, the East Checking Station had been constructed. These two structures marked the east entrance to Zion National Park, which had been accessible from the east since the completion of the Zion-Mt. Carmel Highway in 1930.

Evaluation of Structure: Historic Theme Contributing X Non-Contributing _____
National Register Criteria: A B C D (Include integrity statement)
The East Entrance Sign, built of large, red sandstone blocks with a wooden hanging sign retains its original character and fabric typical of the NPS-Rustic style.

Bibliography: Olivieri, Lance. LCS inventory. 1976:

Representation in Other Surveys: LCS inventory. 1976:

If structure has been removed, how? _____ Date: / /

Report prepared by: Nancy Witherell Date: 10 / 10 / 84

CONTINUATION FROM FRONT SHEET - STRUCTURE NAME Building #3-Horse Shed

LOCATION: Section _____ State _____ **USE:** *CURRENT INTERIOR USE (NPS 28 CODE)* VC
Township _____ County _____ **Original Use** OT-bus shed
Range _____ **Intermediate Uses** _____
PERIOD OF CONSTRUCTION (NPS 28 CODE) HI

OWNERSHIP: Present Owner: NPS **DRAWING NO.** _____
Original Owner: Utah Parks Company **NEGATIVE NO.** ROLL #18, VIEW 6
Intermediate Owner(s): _____

*****PHYSICAL DESCRIPTION*****

TYPE OF STRUCTURE (NPS 28 CODE): RU **CHIMNEYS:** None
ARCHITECTURAL CHARACTER (STYLE): NPS-Rustic
SITE (INCLUDE ORIENTATION OF STRUCTURE): Faces East to entrance **PORCHES:** None
road for Birch Creek garage area
OVERALL BUILDING PLAN (FOOTPRINT): Rectangle **WINDOWS:** At front elevation, a casement window
OVERALL DIMENSIONS: 26'x90'
COMPOSITION (NPS 28 CODE): MT **DOORS:** Open on front (E) elevation
STORIES: 1 Story **ADDITIONS:** None
FOUNDATION: Reinforced concrete
WALLS: Metal corrugated sheeting **INTERIOR PLAN:** Divided into stalls (24 stalls) with
open sides and cement floors.
ROOF: Corrugated metal sheeting; no exposed **INTERIOR FINISHES:** Concrete/dirt floor
roof members

SIGNIFICANT ARCHITECTURAL FEATURES (INCLUDING INTERIOR AND SETTING) FOR PARK PLANNING PURPOSES:

Retains original wall fabric