

CLASSIFIED STRUCTURE FIELD INVENTORY REPORT
(Attach 4" x 5" Black and White Photograph)

REGION RMR PARK/AREA NAME Zion National Park PARK NUMBER 1590

STRUCTURE NAME Residence STRUCTURE NUMBER 6

LOCATION OF STRUCTURE Oak Creek Historic District PARK LOCATION CODE OC

NATIONAL REGISTER DATE: / / MANAGEMENT CATEGORY: (A) (B) (C) (D)

NPS LEGAL INTEREST Fee MANAGEMENT AGREEMENT:

Check all of the following categories for which NPS has treatment responsibility:
Stabilization() Cyclic Maintenance() Routine Maintenance() Approved Ultimate Treatment()

(ROCKY MOUNTAIN REGION USE ONLY)

APPROVED ULTIMATE TREATMENT OR RESOURCE MANAGEMENT PLAN, CULTURAL COMPONENT DESIGNATION:

Preservation (PP)	Restoration (RR)	Reconstruction (CC)
Adaptive Preservation (AP)	Adaptive Restoration (AR)	Adaptive Reconstruction (AC)
Neglect (NG)	Remove (RM)	No Approved Treatment (NO)

Approval Document () Document Date: / /

Estimated Treatment Costs

Stabilization: \$ <u> </u>	Date: <u> </u> / <u> </u> / <u> </u>	Level of Estimate: (A) (B) (C)
Approved Treatment: \$ <u> </u>	Date: <u> </u> / <u> </u> / <u> </u>	Estimator: (Region) (DSC) (A&E)

STATEMENT OF SIGNIFICANCE:

Date of Construction: 5 / 25 / 1951 Date of Alterations: / /
Architect/Designer: Kenneth Saunders Historical Theme(s): NPS Structure
History of Structure: Built from September 1950 through May 1951, under supervision from region three, the contractor for Residences #6, 11, 14, 15, and 27 was David O. Woodbury of St. George, Utah. The residences were constructed in response to an urgent need for housing for Park personnel.

Evaluation of Structure: Historic Theme Contributing Non-Contributing x
National Register Criteria: A B C D (Include integrity statement)

Bibliography: Form 10-768 (maintenance file); Project Completion Report dated December 1, 1951

Representation in Other Surveys:

If structure has been removed, how? Date: / /

Report prepared by: Nancy Witherall Date: 10/10/84

CONTINUATION FROM FRONT SHEET - STRUCTURE NAME Oak Creek Residence #6

LOCATION: Section _____ State _____ **USE:** *CURRENT INTERIOR USE (NPS 28 CODE)* NQ
Township _____ County _____ **Original Use** NQ
Range _____ **Intermediate Uses** NQ
PERIOD OF CONSTRUCTION (NPS 28 CODE) H1

OWNERSHIP: Present Owner: NPS **DRAWING NO.** _____
Original Owner: NPS **NEGATIVE NO.** Roll #17, View 3
Intermediate Owner(s): NPS

*****PHYSICAL DESCRIPTION*****

TYPE OF STRUCTURE (NPS 28 CODE): BU **CHIMNEYS:** None (flue)
ARCHITECTURAL CHARACTER (STYLE): Mission 66 (1950's)
SITE (INCLUDE ORIENTATION OF STRUCTURE): House faces south, **PORCHES:** Patio, cement
to road parallel to Oak Creek
OVERALL BUILDING PLAN (FOOTPRINT): Rectangle **WINDOWS:** Double casement, aluminum sash
OVERALL DIMENSIONS: 24' x 63'
COMPOSITION (NPS 28 CODE): WD **DOORS:** Wood door on primary elevation, back door to patio
STORIES: one **ADDITIONS:** None
FOUNDATION: concrete
WALLS: Rough sawn board and batter over frame construction;
underblock garage **INTERIOR PLAN:** 3 bedroom plan
ROOF: Flat hip roof with gable vents; 3 foot soffit under
roof eaves; asphalt shingle **INTERIOR FINISHES:**

SIGNIFICANT ARCHITECTURAL FEATURES (INCLUDING INTERIOR AND SETTING) FOR PARK PLANNING PURPOSES:

UNITED STATES DEPARTMENT OF THE INTERIOR
NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES
INVENTORY -- NOMINATION FORM

FOR NPS USE ONLY
RECEIVED 2/31/88
DATE ENTERED

CONTINUATION SHEET

ITEM NUMBER 10 PAGE 1

10. BOUNDARY DESCRIPTIONS AND JUSTIFICATION

The area included in the multiple resource nomination is found on the following U.S.G.S. quadrangles:

- Springdale East, Utah Quadrangle, 7.5' series (1980)
- Temple of Sinawava Quadrangle, 7.5' series (1980)
- The Barracks Quadrangle, 7.5' series (1980)

Historic resources are divided into the categories of districts, structures, sites, and buildings, and listed in the order in which they appear in the nomination.

DISTRICTS

1. Oak Creek Historic District
Springdale East Quadrangle

UTM References: 12/323480/4120000
12/324960/4119980

Boundary Description and Justification:

In Section 21, T41S, R10W, starting at the north curb at the end of the residence and continuing south approximately 300 feet to the north bank of Oak Creek; thence northwesterly along said bank approximately 1,400 feet and across the tributary, continuing on the north edge of the utility area parking lot to the east edge of the driveway of said utility road, thence east approximately 200 feet; south approximately 200 feet; west approximately 500 feet; north approximately 200 feet; and east approximately 300 feet to the west edge of the driveway of said utility road, thereby defining a rectangle around the utility building; thence north approximately 400 feet; thence southeast and northeast along the talus slope behind the residences; thence southeast along the talus slope to a point; thence east approximately 1,200 feet along a line 150 feet north of the north curb of the residence road to the retaining wall of the residence (27); thence following the retaining wall to a point; thence east to the north curb of the east end of the residence road which is the point of the beginning.

Contributing buildings are: 5, 8, 9, 10, 21, 24, 25, 26, 76, 77, 78, 79, 80-83, 109, 110, 111, and 112.

CLASSIFIED STRUCTURE FIELD INVENTORY REPORT
(Attach 4" x 5" Black and White Photograph)

REGION RMR PARK/AREA NAME Zion National Park PARK NUMBER 1590
STRUCTURE NAME Residence STRUCTURE NUMBER 11
LOCATION OF STRUCTURE Oak Creek Historic District PARK LOCATION CODE OC
NATIONAL REGISTER _____ DATE: / / MANAGEMENT CATEGORY: (A) (B) (C) (D)
NPS LEGAL INTEREST FEE MANAGEMENT AGREEMENT: _____

Check all of the following categories for which NPS has treatment responsibility:
Stabilization() Cyclic Maintenance() Routine Maintenance() Approved Ultimate Treatment()

(ROCKY MOUNTAIN REGION USE ONLY)

APPROVED ULTIMATE TREATMENT OR RESOURCE MANAGEMENT PLAN, CULTURAL COMPONENT DESIGNATION:

Preservation (PP)	Restoration (RR)	Reconstruction (CC)
Adaptive Preservation (AP)	Adaptive Restoration (AR)	Adaptive Reconstruction (AC)
Neglect (NG)	Remove (RM)	No Approved Treatment (NO)

Approval Document _____ () Document Date: / /
Estimated Treatment Costs _____

Stabilization: \$ _____	Date: <u> / /</u>	Level of Estimate: (A) (B) (C)
Approved Treatment: \$ _____	Date: <u> / /</u>	Estimator: (Region) (DSC) (A&E)

STATEMENT OF SIGNIFICANCE:

Date of Construction: 5/25/1951 Date of Alterations: / /
Architect/Designer: Kenneth Saunders Historical Theme(s): NPS Structure
History of Structure: Supervising Architect, Region Three

Built from September 1950 through May 1951, under supervision from Region Three, the contractor was David O. Woodbury of St. George, Utah. The residences were constructed in response to an urgent need for housing for park personnel.

Evaluation of Structure: Historic Theme Contributing ___ Non-Contributing X
National Register Criteria: A B C D (Include integrity statement)

Bibliography: Form 10-768 (maintenance file): Project Completion Report dated December 1951
Representation in Other Surveys: _____

If structure has been removed, how? _____ Date: / /

Report prepared by: Nancy Witherall Date: 10/10/84

CONTINUATION FROM FRONT SHEET - STRUCTURE NAME Oak Creek Residence #11

LOCATION: Section _____ State _____ **USE:** *CURRENT INTERIOR USE (NPS 28 CODE)* NQ
Township _____ County _____ **Original Use** NQ
Range _____ **Intermediate Uses** NQ

PERIOD OF CONSTRUCTION (NPS 28 CODE) H1

OWNERSHIP: Present Owner: NPS
Original Owner: NPS
Intermediate Owner(s): NPS

DRAWING NO. _____
NEGATIVE NO. Roll #17, View 10

*****PHYSICAL DESCRIPTION*****

TYPE OF STRUCTURE (NPS 28 CODE): BU

CHIMNEYS: Brick chimney

ARCHITECTURAL CHARACTER (STYLE): Mission 66 (1950's)

SITE (INCLUDE ORIENTATION OF STRUCTURE): House faces
southeast, to road parallel to Oak Creek

PORCHES: Patio, cement

OVERALL BUILDING PLAN (FOOTPRINT): Rectangle

OVERALL DIMENSIONS: 24' x 63'

WINDOWS: Double casement windows, aluminum sash; large
large casement windows on front elevation

COMPOSITION (NPS 28 CODE): WD

STORIES: one

DOORS: Wood door on primary elevation; back door to patio

FOUNDATION: concrete

ADDITIONS: None

WALLS: Rough sawn board and batten over frame construction;
concrete block garage

INTERIOR PLAN: 3 bedroom plan

ROOF: flat hipped roof with gable vents; 3 foot soffit
under roof eaves; asphalt shingle

INTERIOR FINISHES:

SIGNIFICANT ARCHITECTURAL FEATURES (INCLUDING INTERIOR AND SETTING) FOR PARK PLANNING PURPOSES:

CLASSIFIED STRUCTURE FIELD INVENTORY REPORT
(Attach 4" x 5" Black and White Photograph)

REGION RMR PARK/AREA NAME Zion National Park PARK NUMBER 1590

STRUCTURE NAME Residence STRUCTURE NUMBER 14

LOCATION OF STRUCTURE Oak Creek Historic District PARK LOCATION CODE OC

NATIONAL REGISTER _____ DATE: / / MANAGEMENT CATEGORY: (A) (B) (C) (D)

NPS LEGAL INTEREST _____ MANAGEMENT AGREEMENT: _____

Check all of the following categories for which NPS has treatment responsibility:

Stabilization() Cyclic Maintenance() Routine Maintenance() Approved Ultimate Treatment()

(ROCKY MOUNTAIN REGION USE ONLY)

APPROVED ULTIMATE TREATMENT OR RESOURCE MANAGEMENT PLAN, CULTURAL COMPONENT DESIGNATION:

Preservation (PP)	Restoration (RR)	Reconstruction (CC)
Adaptive Preservation (AP)	Adaptive Restoration (AR)	Adaptive Reconstruction (AC)
Neglect (NG)	Remove (RM)	No Approved Treatment (NO)

Approval Document _____ () Document Date: / /

Estimated Treatment Costs _____

Stabilization: \$ _____	Date: <u> / /</u>	Level of Estimate: (A) (B) (C)
Approved Treatment: \$ _____	Date: <u> / /</u>	Estimator: (Region) (DSC) (A&E)

STATEMENT OF SIGNIFICANCE:

Date of Construction: 5/25/1951 Date of Alterations: / /

Architect/Designer: Kenneth Saunders Historical Theme(s): _____

History of Structure: Supervising Architect, Region Three

Built from September 1950 through May 1951, under supervision from Region Three. The contractor for Residences #6, 11, 14, 15, and 27 was David O. Woodbury of St. George, Utah. The residences were constructed in response to an urgent need for housing for Park personnel.

Evaluation of Structure: Historic Theme Contributing _____ Non-Contributing X

National Register Criteria: A B C X D (Include integrity statement)

Bibliography: Form 10-768 (maintenance file); Project Completion Report dated December 1951

Representation in Other Surveys: _____

If structure has been removed, how? _____ Date: / /

Report prepared by: Nancy Witherall Date: 10/10/84

CONTINUATION FROM FRONT SHEET - STRUCTURE NAME Oak Creek Residence #14

LOCATION: Section _____ State _____ USE: CURRENT INTERIOR USE (NPS 28 CODE) NO
Township _____ County _____ Original Use NO
Range _____ Intermediate Uses NO
PERIOD OF CONSTRUCTION (NPS 28 CODE) H1

OWNERSHIP: Present Owner: NPS DRAWING NO. _____
Original Owner: NPS NEGATIVE NO. Roll #17, View 2
Intermediate Owner(s): NPS

PHYSICAL DESCRIPTION

TYPE OF STRUCTURE (NPS 28 CODE): BU CHIMNEYS: Brick chimney
ARCHITECTURAL CHARACTER (STYLE): Mission 66 (1950's)
SITE (INCLUDE ORIENTATION OF STRUCTURE): Faces north, to road; Oak Creek runs east-west behind house PORCHES: Patio cement; stoop on front facade with brick floor and wood posts.
OVERALL BUILDING PLAN (FOOTPRINT): Rectangle WINDOWS: Aluminum double casement windows; large casement window on front elevation
OVERALL DIMENSIONS: 24' x 63' DOORS: Wood door on primary facade; back door to patio
COMPOSITION (NPS 28 CODE): WD ADDITIONS: None
STORIES: one INTERIOR PLAN: 3 bedroom plan
FOUNDATION: Concrete INTERIOR FINISHES:
WALLS: Rough sawn board and batten over frame construction; concrete block garage
ROOF: Flat hip roof with gable vents; 3 foot soffit under roof eaves; asphalt shingle

SIGNIFICANT ARCHITECTURAL FEATURES (INCLUDING INTERIOR AND SETTING) FOR PARK PLANNING PURPOSES:

DEC 3 1 1986

CLASSIFIED STRUCTURE FIELD INVENTORY REPORT
(Attach 4" x 5" Black and White Photograph)

REGION RMR PARK/AREA NAME Zion National Park PARK NUMBER 1590

STRUCTURE NAME Residence STRUCTURE NUMBER 15

LOCATION OF STRUCTURE Oak Creek Historic District PARK LOCATION CODE OC

NATIONAL REGISTER _____ DATE: / / MANAGEMENT CATEGORY: (A) (B) (C) (D)

NPS LEGAL INTEREST _____ FEE _____ MANAGEMENT AGREEMENT: _____

Check all of the following categories for which NPS has treatment responsibility:

Stabilization() Cyclic Maintenance() Routine Maintenance() Approved Ultimate Treatment()

(ROCKY MOUNTAIN REGION USE ONLY)

APPROVED ULTIMATE TREATMENT OR RESOURCE MANAGEMENT PLAN, CULTURAL COMPONENT DESIGNATION:

Preservation (PP)	Restoration (RR)	Reconstruction (CC)
Adaptive Preservation (AP)	Adaptive Restoration (AR)	Adaptive Reconstruction (AC)
Neglect (NG)	Remove (RM)	No Approved Treatment (NO)

Approval Document _____ () Document Date: / /

Estimated Treatment Costs _____

Stabilization: \$ _____	Date: <u> / /</u>	Level of Estimate: (A) (B) (C)
Approved Treatment: \$ _____	Date: <u> / /</u>	Estimator: (Region) (DSC) (A&E)

STATEMENT OF SIGNIFICANCE:

Date of Construction: 5/25/51 Date of Alterations: / /

Architect/Designer: Kenneth Saunders Historical Theme(s): _____

History of Structure: Supervising Architect, Region Three

Built from September 1950 through May 1951, under supervision from Region Three.

The contractor for Residence #6, 11, 14, 15, 27 was David O. Woodbury of St. George, Utah. The residences were constructed in response to an urgent need for housing for Park personnel.

Evaluation of Structure: Historic Theme Contributing _____ Non-Contributing x

National Register Criteria: A B C X D (Include integrity statement)

The building was constructed outside the park's period of historical significance.

Bibliography: Form 10-768 (Maintenance File); Project Completion Report dated December 1951.

Representation in Other Surveys: _____

If structure has been removed, how? _____ Date: / /

Report prepared by: Nancy Witherell Date: 10/10/84

LOCATION: Section _____ State _____
 Township _____ County _____
 Range _____

USE: CURRENT INTERIOR USE (NPS 28 CODE) _____ NQ
 Original Use _____ NQ
 Intermediate Uses _____ NQ
 PERIOD OF CONSTRUCTION (NPS 28 CODE) _____ H 1

OWNERSHIP: Present Owner: _____ NPS
 Original Owner: _____ "
 Intermediate Owner(s): _____ "

DRAWING NO. _____
 NEGATIVE NO. Roll 17, View 4

PHYSICAL DESCRIPTION

TYPE OF STRUCTURE (NPS 28 CODE): BU

CHIMNEYS: Brick chimney

ARCHITECTURAL CHARACTER (STYLE): Mission 66 (1950s)

SITE (INCLUDE ORIENTATION OF STRUCTURE): Faces north, to
 road; Oak Creek runs east-west behind building

PORCHES: Patio, cement; stoop on front elevation with
 brick floor and wood posts

OVERALL BUILDING PLAN (FOOTPRINT): Rectangle

WINDOWS: Aluminum double casement windows; large
 casement windows on front elevation

OVERALL DIMENSIONS: 29' x 63'

COMPOSITION (NPS 28 CODE): WD

DOORS: Wood door on primary facade; back door to patio

STORIES: One

FOUNDATION: Concrete

ADDITIONS: None

WALLS: Rough-sawn board and batten over frame
 construction; cinderblock garage

INTERIOR PLAN: Three-bedroom plan

ROOF: Flat hip roof with gable vents; 3-foot soffit
 under roof eaves; asphalt shingle

INTERIOR FINISHES:

SIGNIFICANT ARCHITECTURAL FEATURES (INCLUDING INTERIOR AND SETTING) FOR PARK PLANNING PURPOSES:

DEC 3 1968

CLASSIFIED STRUCTURE FIELD INVENTORY REPORT
(Attach 4" x 5" Black and White Photograph)

REGION RMR PARK/AREA NAME Zion National Park PARK NUMBER 1590

STRUCTURE NAME Residence STRUCTURE NUMBER 27

LOCATION OF STRUCTURE Oak Creek, Historic District PARK LOCATION CODE OC

NATIONAL REGISTER _____ DATE: / / MANAGEMENT CATEGORY: (A) (B) (C) (D)

NPS LEGAL INTEREST _____ FEE _____ MANAGEMENT AGREEMENT: _____

Check all of the following categories for which NPS has treatment responsibility:

Stabilization() Cyclic Maintenance() Routine Maintenance() Approved Ultimate Treatment()

(ROCKY MOUNTAIN REGION USE ONLY)

APPROVED ULTIMATE TREATMENT OR RESOURCE MANAGEMENT PLAN, CULTURAL COMPONENT DESIGNATION:

Preservation (PP)	Restoration (RR)	Reconstruction (CC)
Adaptive Preservation (AP)	Adaptive Restoration (AR)	Adaptive Reconstruction (AC)
Neglect (NG)	Remove (RM)	No Approved Treatment (NO)

Approval Document _____ () Document Date: / /

Estimated Treatment Costs _____

Stabilization: \$ _____ Date: / /

Approved Treatment: \$ _____ Date: / /

Level of Estimate: (A) (B) (C)
Estimator: (Region) (DSC) (A&E)

STATEMENT OF SIGNIFICANCE:

Date of Construction: 5/25/51 Date of Alterations: / /

Architect/Designer: Kenneth Saunders Historical Theme(s): _____

History of Structure: Supervising Architect, Region Three

Built from September 1950 through May 1951, under supervision from Region Three.
The contractor for Residences #6, 11, 14, 15, 27 was David O. Woodbury of St. George, Utah. The residences were constructed in response to an urgent need for housing for park personnel.

Evaluation of Structure: Historic Theme Contributing ___ Non-Contributing X

National Register Criteria: A B C D (Include integrity statement)

The building was constructed outside the park's period of historical significance.

Bibliography: Form 10-768 (Maintenance File): Project Completion Report dated

December 1951.

Representation in Other Surveys: _____

If structure has been removed, how? _____ Date: / /

Report prepared by: Nancy Witherell Date: 10/10/84

LOCATION: Section _____ State _____ USE: CURRENT INTERIOR USE (NPS 28 CODE) NQ
 Township _____ County _____ Original Use _____ NQ
 Range _____ Intermediate Uses _____ NQ
 PERIOD OF CONSTRUCTION (NPS 28 CODE) H 1

OWNERSHIP: Present Owner: _____ NPS DRAWING NO. _____
 Original Owner: _____ " NEGATIVE NO. ROLL #17, VIEW 11
 Intermediate Owner(s): _____ "

PHYSICAL DESCRIPTION

TYPE OF STRUCTURE (NPS 28 CODE): BU CHIMNEYS: Brick chimney
 ARCHITECTURAL CHARACTER (STYLE): Mission 66 (1950s)
 SITE (INCLUDE ORIENTATION OF STRUCTURE): House faces southeast, to road which runs parallel to Oak Creek PORCHES: Patio, cement; stoop on front elevation
 OVERALL BUILDING PLAN (FOOTPRINT): Rectangle WINDOWS: Aluminum double casement windows; large casement window on front elevation
 OVERALL DIMENSIONS: 24' x 63'
 COMPOSITION (NPS 28 CODE): WD DOORS: Wood door on primary elevation; Back door to patio
 STORIES: One-Story ADDITIONS: None
 FOUNDATION: Concrete
 WALLS: Rough-sawn board and batten over frame construction; cinderblock garage INTERIOR PLAN: Three-bedroom plan
 ROOF: Flat hip roof with gable vents; 3-foot soffit under eaves; asphalt shingle INTERIOR FINISHES:

SIGNIFICANT ARCHITECTURAL FEATURES (INCLUDING INTERIOR AND SETTING) FOR PARK PLANNING PURPOSES:



LCS No. #6

Photo No. Roll #17 View 3

Subject Residence

Descrip. of View View from West

Location of Subject Oak Creek Residential
Historic District

Location of Negative Rm 20

By Nancy W. Therrall Date 8/84



LCS No. #14

Photo No. View 2 Roll #17

Subject Residence

Descrip. of View View from East

Location of Subject Oak Creek Residential
Historic District

Location of Negative RMRO

By Nancy Witherall Date 8/84



LCS No. 15
Photo No. Roll #17, View 4
Subject Residence

Descrip. of View West
Location of Subject Oak Creek N.D.

Location of Negative RMRO

By Nancy Wetherall Date 8/84